



Print Report

Experian AutoCheck Report

Report run: 07/09/2026 18:37:37 EDT

2013 Nissan LEAF S / SL / SV

Hatchback 4D (Electric 107 107)

VIN:

1N4AZ0CP9DC424452

Class:

Car - Compact

Country of Assembly:

United States

Vehicle Age:

13 year(s)

Estimated In Service:

12/04/2013

Last Reported Odometer:

83,976 (07/08/2026)

[View Vehicle Label](#)

Owners - 4

Number of Owners

Vehicle Usage

Lease

x

Window Sticker

Loading window sticker...



[Download PDF](#)

Vehicle History at a Glance

vhg-title-brand-no-issue

State Title Brand

icon-success-pass

Clean

auction brand icon

Auction Brand / Issues

Structural Damage


icon-warning

Auction Issue Reported


By accessing our site, you acknowledge that we and our partners use cookies and similar technologies as described in our [Privacy Policy](#), and you agree to our [Terms of Use](#).

Got it


Structural Damage




Severe




Open Recall Check




No Open Recalls



Insurance Loss / Transfer




No Issue




Odometer Check

Last reported odometer:


83,976 (07/08/2026)




No Issue



Certified Pre-Owned




No CPO Info Available




Service / Repair

1 Service Record(s) Reported



No Issue



Additional History

Lien Reported



Events Reported



This vehicle is not AutoCheck Assured™

This vehicle is not AutoCheck Assured™ due to a state title brands or other major problems reported.

By accessing our site, you acknowledge that we and our partners use cookies and similar technologies as described in our [Privacy Policy](#), and you agree to our [Terms of Use](#).

-  accident-airbag-deployed-off Airbag Deployed
-  accident-structural-damage-on Structural Damage
-  accident-overturned-off Overturned
-  accident-severe-red Severe

Damage Date	Damage Type	Severity
04/17/2015	Collision	Unknown
08/03/2017	Structural Damage	Severe

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

 Service History Summary Icon [Service History](#) [Back To Top](#)

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

 Service History Summary Icon

Regular Oil Changes

Information not available.

 Service History Summary Icon

Fluids Maintained

Information not available.

 Service History Summary Icon

Brakes Maintained

Information not available.

 Service History Summary Icon

Tires Maintained

Information not available.

 Service History Summary Icon

A/C & Climate Control

- **1** A/C services reported
- A/C system last serviced **06/27/2023**

 Service History Summary Icon

By accessing our site, you acknowledge that we and our partners use cookies and similar technologies as described in our [Privacy Policy](#), and you agree to our [Terms of Use](#).

- Battery replaced on **06/27/2023**

OEM Recommended Services

 Service History Summary Icon

80000 Mile Service

- Adjust Tires to Proper Tire Pressure
- Clean & Adjust Brakes
- Inspect & Reset TPMS Monitor

 Service History Summary Icon

85000 Mile Service Not Yet Due

- Adjust Tires to Proper Tire Pressure
- Clean & Adjust Brakes
- Inspect & Reset TPMS Monitor

[See more](#)

OEM Recommended Services



Please contact your local dealer or visit the OEM's website for details.

 Service History Summary Icon

80000 Mile Service

- Adjust Tires to Proper Tire Pressure
- Clean & Adjust Brakes
- Inspect & Reset TPMS Monitor
- Install Premium Fuel System Additive
- Install Windshield Washer Solvent
- Perform Multi-Point Inspection
- Replace Synthetic Oil & Filter
- Rotate Tires

By accessing our site, you acknowledge that we and our partners use cookies and similar technologies as described in our [Privacy Policy](#), and you agree to our [Terms of Use](#).

- Adjust Tires to Proper Tire Pressure
- Clean & Adjust Brakes
- Inspect & Reset TPMS Monitor
- Install Premium Fuel System Additive
- Install Windshield Washer Solvent
- Perform Multi-Point Inspection
- Replace Synthetic Oil & Filter
- Rotate Tires

Close

 Odometer Check [Back To Top](#)

 icon-success-pass

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

 icon-success-pass

State Title Odometer Check

No issues reported

 icon-success-pass

Auction Odometer Check

No issues reported

 icon-success-pass

Odometer Calculation Check

No issues reported

 Detailed Vehicle History [Back To Top](#)

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2013 Nissan LEAF S / SL / SV (1N4AZ0CP9DC424452) **Report Run Date:** 07/09/2026 18:37:37 EDT

2013

[Vehicle Prep and Other Pre-Titling Events](#)

Preparation Date: 12/2013



Event Date	Location	Odometer	Data Source	Details
12/04/2013			Independent Source	Vehicle Manufactured and Shipped to Dealer
12/04/2013	CA		Independent Source	Vehicle Manufactured and Shipped to Dealer
04/24/2014	CA	6	Motor Vehicle Dept	Odometer Reading from DMV

By accessing our site, you acknowledge that we and our partners use cookies and similar technologies as described in our [Privacy Policy](#), and you agree to our [Terms of Use](#).

2014

Owner 1

Location: CA
Owned From: 06/2014
Usage: Lease

Event Date	Location	Odometer	Data Source	Details
06/02/2014	SAN JOSE, CA		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
06/03/2014	SACRAMENTO, CA		Motor Vehicle Dept.	Title(Leased Vehicle)(Lien Reported)
06/12/2014	SACRAMENTO, CA		Motor Vehicle Dept.	Title(Leased Vehicle)(Lien Reported)
04/17/2015	CA		Police Report	Rear Impact Collision Accident Reported(Report #:15-107-0925) 
06/01/2015	CA		State Agency	Accident Reported, Event Date is Date Reported to AutoCheck
07/05/2017	PACIFIC NW REGION	30,399	Auto Auction	Reported at Auto Auction
07/31/2017	PACIFIC NW REGION	30,399	Auto Auction	Reported at Auto Auction as Manufacturer Vehicle
08/03/2017	PACIFIC NW REGION		Auto Auction	Auction Announced as Structural Damage 
08/07/2017	OR	30,431	Motor Vehicle Dept.	Odometer Reading from DMV

2017

Owner 2

Location: OR
Owned From: 08/2017
Usage: Personal

Event Date	Location	Odometer	Data Source	Details
08/18/2017	BEAVERTON, OR		Motor Vehicle Dept.	Title Registration Event/Renewal
09/13/2017	OR	37,832	Motor Vehicle Dept.	Odometer Reading from DMV

2017

Location: OR
Owned From: 10/2017
Usage: Personal

Event Date	Location	Odometer	Data Source	Details
10/02/2017	PORTLAND, OR		Motor Vehicle Dept.	Title Registration Event/Renewal
08/12/2019	PORTLAND, OR		Motor Vehicle Dept.	Registration Event/Renewal
08/08/2021	PORTLAND, OR		Motor Vehicle Dept.	Registration Event/Renewal
04/27/2023	PORTLAND, OR		Motor Vehicle Dept.	Registration Event/Renewal
06/27/2023	WILSONVILLE, OR	69,474	Service Record	Heat or Air Conditioning Serviced Battery Serviced or Replaced Multiple Point Vehicle Inspection Electrical System Serviced
08/04/2023	PORTLAND, OR		Motor Vehicle Dept.	Registration Event/Renewal

2025

[Owner 4](#)
Location: OR
Owned From: 01/2025
Usage: Personal

Event Date	Location	Odometer	Data Source	Details
01/31/2025	PORTLAND, OR		Motor Vehicle Dept.	Registration Event/Renewal
02/03/2025	PORTLAND, OR	71,375	Motor Vehicle Dept.	Title
07/29/2025	PORTLAND, OR		Motor Vehicle Dept.	Registration Event/Renewal
07/08/2026	PACIFIC NW REGION	83,976	Auto Auction	Reported at Auto Auction

2013

[Vehicle Prep and Other Pre-Titling Events](#)

Preparation Date: 12/2013

Event Date - 12/04/2013

Location -

Data Source - Independent Source

Details - Vehicle Manufactured and Shipped to Dealer

Event Date - 12/04/2013

Location - CA

Data Source - Independent Source

Event Date - 04/24/2014

Location - CA

Odometer - 6

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

2014

[Owner 1](#)

Location: CA

Owned From: 06/2014

Usage: Lease

Event Date - 06/02/2014

Location - SAN JOSE, CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal(Leased Vehicle)

Event Date - 06/03/2014

Location - SACRAMENTO, CA

Data Source - Motor Vehicle Dept.

Details - Title(Leased Vehicle)(Lien Reported)

Event Date - 06/12/2014

Location - SACRAMENTO, CA

Data Source - Motor Vehicle Dept.

Details - Title(Leased Vehicle)(Lien Reported)

Event Date - 04/17/2015 

Location - CA

Data Source - Police Report

Details - Rear Impact Collision

Accident Reported (Report #145-107-0005)

Location - CA

Data Source - State Agency

Details - Accident Reported, Event Date is Date Reported to AutoCheck

Event Date - 07/05/2017

Location - PACIFIC NW REGION

Odometer - 30,399

Data Source - Auto Auction

Details - Reported at Auto Auction

Event Date - 07/31/2017

Location - PACIFIC NW REGION

Odometer - 30,399

Data Source - Auto Auction

Details - Reported at Auto Auction as Manufacturer Vehicle

Event Date - 08/03/2017 

Location - PACIFIC NW REGION

Data Source - Auto Auction

Details - Auction Announced as Structural Damage

Event Date - 08/07/2017

Location - OR

Odometer - 30,431

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

2017

[Owner 2](#)

Location - OR

Event Date - 08/18/2017

Location - BEAVERTON, OR

Data Source - Motor Vehicle Dept.

Details - Title
Registration Event/Renewal

Event Date - 09/13/2017

Location - OR

Odometer - 37,832

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

2017

[Owner 3](#)

Location: OR
Owned From: 10/2017
Usage: Personal

Event Date - 10/02/2017

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Title
Registration Event/Renewal

Event Date - 08/12/2019

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 08/08/2021

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 06/27/2023

Location - WILSONVILLE, OR

Odometer - 69,474

Data Source - Service Record

Details - Heat or Air Conditioning Serviced

Battery Serviced or Replaced

Multiple Point Vehicle Inspection

Electrical System Serviced

Event Date - 08/04/2023

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

2025

[Owner 4](#)

Location: OR

Owned From: 01/2025

Usage: Personal

Event Date - 01/31/2025

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 02/03/2025

Location - PORTLAND, OR

Odometer - 71,375

Event Date - 07/29/2025

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 07/08/2026

Location - PACIFIC NW REGION

Odometer - 83,976

Data Source - Auto Auction

Details - Reported at Auto Auction

Warranty Check

[Warranty Check](#)[Back To Top](#)

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Enter Mileage:

miles

Show My Coverage

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-	 Expired	36 months / 36000 miles
				96 months / 100000 miles
Battery 	16,024	-	 Expired	Lithium ion battery.
Corrosion 	-	-	 Expired	60 months / Unlimited miles
Powertrain 	-	-	 Expired	60 months / 60000 miles
Roadside Assistance 	-	-	 Expired	36 months / 36000 miles
				Towing only.
Safety Restraint 	-	-	 Expired	120 months / Unlimited miles
				Nissan covers supplied seat belt component, that fails to function properly during normal use.

This Vehicle's Glossary[Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

Term

Vehicle History at a Glance

A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Auction Issue

Vehicle History at a Glance

This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Accident/Damage Check

Vehicle History at a Glance

This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Insurance Loss/Title Transfer

Vehicle History at a Glance

This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Additional History

Vehicle History at a Glance

This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Odometer Check

Vehicle History at a Glance

This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Structural Damage or Structural Alteration

Accident / Damage

"Structural" or "Frame" damage refers to a vehicle's structure or a specific structural or frame component, and may apply to a conventional frame, "Unibody", and "Unibody on Frame" structures. Structural Alteration -An alteration to the vehicle's structure including a lengthened or shortened frame, a modified suspension, or the installation or removal of after-market accessories. For additional information on these types of reported information, please see the [National Auction Automotive Association Arbitration Policy 2025](#).

Loan/Lien

Additional History

A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Lease Use

Owner Type

Vehicle was registered as lease vehicle.

Accident

events will vary. In all events AutoCheck recommends that prospective vehicle purchasers conduct a detailed vehicle inspection prior to purchase of a pre-owned vehicle.

Term - State Title Brand

Section Location - Vehicle History at a Glance

Definition - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Term - Auction Issue

Section Location - Vehicle History at a Glance

Definition - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Accident/Damage Check

Section Location - Vehicle History at a Glance

Definition - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Term - Insurance Loss/Title Transfer

Section Location - Vehicle History at a Glance

Definition - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Term - Additional History

Section Location - Vehicle History at a Glance

Definition - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Term - Odometer Check

Section Location - Vehicle History at a Glance

By accessing our site, you acknowledge that we and our partners use cookies and similar technologies as described in our [Privacy Policy](#), and you agree to our [Terms of Use](#).

sequence of reported odometer readings to determine if there are any potential discrepancies.

Term - Structural Damage or Structural Alteration

Section Location - Accident / Damage

Definition - "Structural" or "Frame" damage refers to a vehicle's structure or a specific structural or frame component, and may apply to a conventional frame, "Unibody", and "Unibody on Frame" structures. Structural Alteration -An alteration to the vehicle's structure including a lengthened or shortened frame, a modified suspension, or the installation or removal of after-market accessories. For additional information on these types of reported information, please see the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Loan/Lien

Section Location - Additional History

Definition - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Term - Lease Use

Section Location - Owner Type

Definition - Vehicle was registered as lease vehicle.

Term - Accident

Section Location - Accident / Damage

Definition - A state or municipality has reported an accident or collision for this vehicle that may or may not have sustained damage. Not all damage events are reported to AutoCheck and the damage severity of reported events will vary. In all events AutoCheck recommends that prospective vehicle purchasers conduct a detailed vehicle inspection prior to purchase of a pre-owned vehicle.