

Print Report



Experian AutoCheck Report

Report run: 07/13/2026 14:39:20 EDT

2014 Kia Soul +

SUV 4D (2.0L I4 DI Gasoline)

VIN:

KNDJP3A51E7038041

Class:

CUV - Compact

Country of Assembly:

South Korea

Vehicle Age:

12 year(s)

Estimated In Service:

04/21/2014

Last Reported Odometer:

109,417 (04/30/2026)

[View Vehicle Label](#)

Owners - 2

Number of Owners

Vehicle Usage

Personal

x

Window Sticker

Loading window sticker...



[Download PDF](#)

Vehicle History at a Glance

vhg-title-brand-no-issue

State Title Brand

icon-more-information

Clean

auction brand icon

Auction Brand / Issues


icon-success-pass

No Issue


vhg-accident-damage-no-issue

Accident / Damage

No Accidents or Damage Reported




No Issue




Open Recall Check




1 Open Recall(s)



Insurance Loss / Transfer




No Issue




Odometer Check

Last reported odometer:


109,417 (04/30/2026)




No Issue



Certified Pre-Owned




No CPO Info Available




Service / Repair

18 Service Record(s) Reported



No Issue



Additional History

Lien Reported






Events Reported



This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

[Learn More](#)



 accident-overturned-off Overturned

 accident-severe-off No Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.

 Open Safety Recall Open Recall Check [Back To Top](#)

 More Information

Information Reported: AutoCheck found 1 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date

Recall Type

NHTSA / OEM Recall No.

Campaign Description

02/18/2022

Unspecified

22V096 / SC229

SC229 ACU S/W UPDATE

Status: Remedy Unknown

Recall Date - 02/18/2022

Recall Type - Unspecified

NHTSA / OEM Recall No. - 22V096 / SC229

Campaign Description - SC229 ACU S/W UPDATE

Status: Remedy Unknown

[More information](#) including remedy or risk factors. Locate your nearest authorized [Kia Dealer](#) to schedule repair.

 Service History Summary Icon Service History [Back To Top](#)

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

 Service History Summary Icon

Regular Oil Changes

- **6** oil services reported
- Last oil service reported **10/25/2021**

 Service History Summary Icon

Fluids Maintained

- **5** coolant flushes
- Last fluid maintained **10/25/2021**

 Service History Summary Icon

Brakes Maintained

- **3** brake pad replacements
- Brake last maintained on **05/30/2019**

 Service History Summary Icon

Tires Maintained

Information not available.

 Service History Summary Icon

A/C & Climate Control

- **2** A/C services reported
- A/C system last serviced **03/22/2019**

 Service History Summary Icon

Other Services

- Cabin air filter replaced on **03/22/2019**

OEM Recommended Services

 Service History Summary Icon

105000 Mile Service

- Check if Fuel Additive is required (Only necessary if TOP TIER Detergent Gasoline is not available. Add'l cost if needed)
- Inspect air cleaner filter
- Inspect air conditioning compressor, air conditioner refrigerant and performance (if equipped)

 Service History Summary Icon

112500 Mile Service Not Yet Due

- Check if Fuel Additive is required (Only necessary if TOP TIER Detergent Gasoline is not available. Add'l cost if needed)
- Inspect manual transaxle fluid (if equipped)
- Replace engine oil and filter

[See more](#)

OEM Recommended Services



Please contact your local dealer or visit the OEM's website for details.



Service History Summary Icon

105000 Mile Service

- Check if Fuel Additive is required (Only necessary if TOP TIER Detergent Gasoline is not available. Add'l cost if needed)
- Inspect air cleaner filter
- Inspect air conditioning compressor, air conditioner refrigerant and performance (if equipped)
- Inspect battery condition
- Inspect brake/clutch fluid
- Inspect brake fluid
- Inspect brake lines, hoses and connections
- Inspect brake pedal and operation
- Inspect chassis/body nuts and bolts
- Inspect cooling system
- Inspect disc brakes and pads
- Inspect drive belts
- Inspect drive shafts and boots
- Inspect drum brakes and linings
- Inspect exhaust pipe and muffler
- Inspect front suspension ball joints
- Inspect fuel tank, cap, lines, and hoses
- Inspect parking brake
- Inspect steering operation and linkage
- Inspect suspension mounting bolts
- Lubricate all locks and hinges
- Replace climate control air filter
- Replace engine oil and filter
- Replace spark plugs
- Rotate tires, inspect tread wear, and tire pressure



Service History Summary Icon

- Check if Fuel Additive is required (Only necessary if TOP TIER Detergent Gasoline is not available. Add'l cost if needed)
- Inspect manual transaxle fluid (if equipped)
- Replace engine oil and filter
- Rotate tires, inspect tread wear, and tire pressure

Close

 Odometer Dial Odometer Check [Back To Top](#)

 icon-success-pass

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

 icon-success-pass

State Title Odometer Check

No issues reported

 icon-success-pass

Auction Odometer Check

No issues reported

 icon-success-pass

Odometer Calculation Check

No issues reported

 Detailed Vehicle History Icon Detailed Vehicle History [Back To Top](#)

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2014 Kia Soul + (KNDJP3A51E7038041) **Report Run Date:** 07/13/2026 14:39:20 EDT

2014

[Vehicle Prep and Other Pre-Titling Events](#)

Location: OR

Preparation Date: 04/2014

Event Date	Location	Odometer	Data Source	Details
04/21/2014	OR	13	Motor Vehicle Dept.	Odometer Reading from DMV

2014

[Owner 1](#)

Location: OR

Owned From: 05/2014

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
05/28/2014	HAPPY VALLEY, OR		Motor Vehicle Dept.	Title(Lien Reported) Registration Event/Renewal Steering System Serviced Cooling System Serviced Air Filter Changed Multiple Point Vehicle Inspection
11/15/2017	GLADSTONE, OR	58,242	Service Record	Engine Serviced Wipers Replaced And/Or Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
04/26/2018	OREGON CITY, OR		Motor Vehicle Dept.	Registration Event/Renewal
04/26/2018	OR		State Agency	Passed Emission Inspection Steering System Serviced Multiple Point Vehicle Inspection
07/16/2018	GLADSTONE, OR	64,812	Service Record	Engine Serviced Recommended Maintenance Performed Drive Line Serviced Lube, Oil And/Or Filter Changed Steering System Serviced Cooling System Serviced Air Filter Changed Multiple Point Vehicle Inspection
03/22/2019	GLADSTONE, OR	68,226	Service Record	Engine Serviced Wipers Replaced And/Or Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
05/30/2019	GLADSTONE, OR	69,498	Service Record	Brakes Serviced
04/18/2020	OR	74,653	Service Record	Vehicle Inspected
04/18/2020	BEAVERTON, OR		Service Record	Multiple Point Vehicle Inspection
04/18/2020	OR		Service Record	Vehicle Recall Service Performed
04/18/2020	BEAVERTON, OR		Service Record	Engine Serviced Vehicle Detailed Wipers Replaced And/Or Serviced
04/18/2020	OR		Service Record	Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced Promotional Service Performed

2020

[Owner 2](#)

Location: OR

Owned From: 04/2020

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
04/29/2020	OR		Motor Vehicle Dept.	Registration Event/Renewal
04/30/2020	OR	74,583 †	Motor Vehicle Dept.	Title
10/17/2020	OR	75,852	Service Record	Vehicle Inspected
10/17/2020	BEAVERTON, OR		Service Record	Multiple Point Vehicle Inspection
10/17/2020	OR		Service Record	Vehicle Recall Service Performed
10/17/2020	BEAVERTON, OR		Service Record	Engine Serviced
10/17/2020	OR		Service Record	Vehicle Detailed
10/17/2020	BEAVERTON, OR		Service Record	Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
10/17/2020	OR		Service Record	Promotional Service Performed
01/07/2021	OR		Motor Vehicle Dept.	Registration Event/Renewal
10/23/2021	BEAVERTON, OR	79,050	Service Record	Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
10/25/2021	OR		Service Record	Vehicle Inspected Vehicle Recall Service Performed Vehicle Detailed Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced Promotional Service Performed
02/18/2022			Manufacturer	Manufacturer Recall NHTSA Recall 22V096 / Mfr. Recall SC229 SC229 ACU S/W UPDATE LOCATE YOUR NEAREST AUTHORIZED KIA DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
05/25/2022	OR		Motor Vehicle Dept.	Registration Event/Renewal
12/12/2023			Manufacturer	Manufacturer Service Bulletin Mfr. Recall CS2311A Customer Satisfaction Campaign: CS2311A ANTI-THEFT IGNITION PROTECTOR LOCATE YOUR NEAREST AUTHORIZED KIA DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
05/02/2024	BEAVERTON, OR		Motor Vehicle Dept.	Registration Event/Renewal
05/02/2024	OR	88,658	Motor Vehicle Dept.	Passed Emission Inspection

Event Date	Location	Odometer	Data Source	Details
04/30/2026	BEAVERTON, OR		Motor Vehicle Dept.	Registration Event/Renewal
04/30/2026	OR	109,417	Motor Vehicle Dept.	Passed Emission Inspection

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

2014

[Vehicle Prep and Other Pre-Titling Events](#)

Location: OR

Preparation Date: 04/2014

Event Date - 04/21/2014

Location - OR

Odometer - 13

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

2014

[Owner 1](#)

Location: OR

Owned From: 05/2014

Usage: Personal

Event Date - 05/28/2014

Location - HAPPY VALLEY, OR

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)
Registration Event/Renewal

Event Date - 11/15/2017

Location - GLADSTONE, OR

Odometer - 58,242

Data Source - Service Record

Details - Steering System Serviced
Cooling System Serviced
Air Filter Changed
Multiple Point Vehicle Inspection
Engine Serviced
Wipers Replaced And/Or Serviced
Brakes Serviced
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Vehicle Fluids Serviced

Event Date - 04/26/2018

Location - OREGON CITY, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/26/2018

Location - OR

Data Source - State Agency

Details - Passed Emission Inspection

Event Date - 07/16/2018

Location - GLADSTONE, OR

Odometer - 64,812

Data Source - Service Record

Details - Steering System Serviced
Multiple Point Vehicle Inspection
Engine Serviced
Recommended Maintenance Performed
Drive Line Serviced
Lube, Oil And/Or Filter Changed

Event Date - 03/22/2019

Location - GLADSTONE, OR

Odometer - 68,226

Data Source - Service Record

Details - Steering System Serviced
Cooling System Serviced
Air Filter Changed
Multiple Point Vehicle Inspection
Engine Serviced
Wipers Replaced And/Or Serviced
Brakes Serviced
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Vehicle Fluids Serviced

Event Date - 05/30/2019

Location - GLADSTONE, OR

Odometer - 69,498

Data Source - Service Record

Details - Brakes Serviced

Event Date - 04/18/2020

Location - OR

Odometer - 74,653

Data Source - Service Record

Details - Vehicle Inspected

Event Date - 04/18/2020

Location - BEAVERTON, OR

Data Source - Service Record

Details - Multiple Point Vehicle Inspection

Event Date - 04/18/2020

Location - OR

Data Source - Service Record

Details - Vehicle Recall Service Performed

Event Date - 04/18/2020

Location - BEAVERTON, OR

Data Source - Service Record

Details - Engine Serviced

Event Date - 04/18/2020

Location - OR

Data Source - Service Record

Details - Vehicle Detailed

Wipers Replaced And/Or Serviced

Tires or Wheels Service Performed

Lube, Oil And/Or Filter Changed

Vehicle Fluids Serviced

Promotional Service Performed

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

2020

[Owner 2](#)

Location: OR

Owned From: 04/2020

Usage: Personal

Event Date - 04/29/2020

Location - OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/30/2020

Location - OR

Odometer - 74,583 †

Data Source - Motor Vehicle Dept.

Details - Title

Event Date - 10/17/2020

Location - OR

Odometer - 75,852

Data Source - Service Record

Details - Vehicle Inspected

Event Date - 10/17/2020

Location - BEAVERTON, OR

Data Source - Service Record

Details - Multiple Point Vehicle Inspection

Event Date - 10/17/2020

Location - OR

Data Source - Service Record

Details - Vehicle Recall Service Performed

Event Date - 10/17/2020

Location - BEAVERTON, OR

Data Source - Service Record

Details - Engine Serviced

Event Date - 10/17/2020

Location - OR

Data Source - Service Record

Details - Vehicle Detailed

Event Date - 10/17/2020

Location - BEAVERTON, OR

Data Source - Service Record

Details - Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Vehicle Fluids Serviced

Event Date - 10/17/2020

Location - OR

Data Source - Service Record

Details - Promotional Service Performed

Event Date - 01/07/2021

Location - OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 10/23/2021

Location - BEAVERTON, OR

Odometer - 79,050

Data Source - Service Record

Details - Multiple Point Vehicle Inspection

Engine Serviced

Tires or Wheels Service Performed

Lube, Oil And/Or Filter Changed

Vehicle Fluids Serviced

Event Date - 10/25/2021

Location - OR

Data Source - Service Record

Details - Vehicle Inspected

Vehicle Recall Service Performed

Vehicle Detailed

Electrical System Serviced

Tires or Wheels Service Performed

Lube, Oil And/Or Filter Changed

Vehicle Fluids Serviced

Promotional Service Performed

Event Date - 02/18/2022

Location -

Data Source - Manufacturer

Details - Manufacturer Recall

NHTSA Recall 22V096 / Mfr. Recall SC229

SC229 ACU S/W UPDATE

LOCATE YOUR NEAREST AUTHORIZED

[KIA DEALER](#) TO SCHEDULE REPAIR.

Status: Remedy Unknown

Event Date - 05/25/2022

Location - OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/12/2023

Location -

Data Source - Manufacturer

Details - Manufacturer Service Bulletin
Mfr. Recall CS2311A
Customer Satisfaction Campaign: CS2311A ANTI-THEFT IGNITION PROTECTOR
LOCATE YOUR NEAREST AUTHORIZED
[KIA DEALER](#) TO SCHEDULE REPAIR.
Status: Remedy Unknown

Event Date - 05/02/2024

Location - BEAVERTON, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 05/02/2024

Location - OR

Odometer - 88,658

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 04/30/2026

Location - BEAVERTON, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/30/2026

Location - OR

Odometer - 109,417

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

Warranty Check Icon Warranty Check[Back To Top](#)

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Enter Mileage:

miles

[Show My Coverage](#)

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic ⓘ	-	-	 Expired	60 months / 60000 miles
Battery ⓘ	-	-	-	Contact a certified dealer to verify coverage
Corrosion ⓘ	-	-	 Expired	60 months / 100000 miles
				120 months / 100000 miles
Powertrain ⓘ	-	-	 Expired	Original owner 120 Months/100,000 Miles Second and Subsequent Owners 60 Months/60,000 Miles.
Roadside Assistance ⓘ	-	-	 Expired	60 months / 60000 miles
Safety Restraint ⓘ	-	-	-	Contact a certified dealer to verify coverage

This Vehicle's Glossary[Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

Term

Section Location

Definition

State Title Brand

Vehicle History at a Glance

A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Auction Issue

Vehicle History at a Glance

This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Accident/Damage Check

Vehicle History at a Glance

This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Insurance Loss/Title Transfer

Vehicle History at a Glance

This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Additional History

Vehicle History at a Glance

This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Odometer Check

Vehicle History at a Glance

This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Open Recall Check

Vehicle History at a Glance

This section lists any open safety or emission recalls on the vehicle that may need to be fulfilled.

Loan/Lien

Additional History

A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Personal Use

Owner Type

This vehicle was driven for personal use.

Open Recall

Open Recall Check

A recall is considered 'open' for a vehicle when it has not received the required service to correct the identified recall. The vehicle will need to be taken to a repair center that has been authorized by the manufacturer to correct any open recall conditions.

Term - State Title Brand

Section Location - Vehicle History at a Glance

Definition - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Term - Auction Issue

Section Location - Vehicle History at a Glance

Definition - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Accident/Damage Check

Section Location - Vehicle History at a Glance

Definition - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Term - Insurance Loss/Title Transfer

Section Location - Vehicle History at a Glance

Definition - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Term - Additional History

Section Location - Vehicle History at a Glance

Definition - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Term - Odometer Check

Section Location - Vehicle History at a Glance

Definition - This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Term - Open Recall Check

Section Location - Vehicle History at a Glance

Definition - This section lists any open safety or emission recalls on the vehicle that may need to be fulfilled.

Term - Loan/Lien

Section Location - Additional History

Definition - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Term - Personal Use

Section Location - Owner Type

Definition - This vehicle was driven for personal use.

Term - Open Recall

Section Location - Open Recall Check

Definition - A recall is considered 'open' for a vehicle when it has not received the required service to correct the identified recall. The vehicle will need to be taken to a repair center that has been authorized by the manufacturer to correct any open recall conditions.