

Print Report



Experian AutoCheck Report

Report run: 07/13/2026 14:41:03 EDT

2013 Mercedes-Benz E-Class E 350

Convertible 2D (3.5L V6 DI Gasoline)

VIN:

WDDKK5KF2DF207841

Class:

Car - Compact Luxury

Country of Assembly:

Germany

Vehicle Age:

13 year(s)

Estimated In Service:

03/14/2013

Last Reported Odometer:

120,368 (03/20/2026)

[View Vehicle Label](#)

Owners - 2

Number of Owners

Vehicle Usage

Lease

x

Window Sticker

Loading window sticker...



[Download PDF](#)

Vehicle History at a Glance

vhg-title-brand-no-issue

State Title Brand

icon-success-pass

Clean

auction brand icon

Auction Brand / Issues

icon-success-pass

No Issue

vhg-accident-damage-issue-found

Accident / Damage

icon-warning

Damage Reported

 recall check icon

Open Recall Check

 icon-success-pass

No Open Recalls

 vhg-insurance-loss-title-no-issue

Insurance Loss / Transfer

 icon-success-pass

No Issue

 vhg-odometer-check-no-issue

Odometer Check

Last reported odometer:

120,368 (03/20/2026)

 icon-success-pass

No Issue

 cpo icon

Certified Pre-Owned

 icon-success-pass

No CPO Info Available

 service repair icon

Service / Repair

10 Service Record(s) Reported

 icon-success-pass

No Issue

 vhg-additional-history-issue-found

Additional History

Lien Reported

 icon-more-information

Events Reported

 vhg-title-brand-no-issue

This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

[Learn More](#)

 damage icon Accident & Damage [Back To Top](#)

 accident-car-outline  poi  poi  poi

 accident-airbag-deployed-off Airbag Deployed

 accident-structural-damage-off Structural Damage

 accident-overturned-off Overturned

 accident-severe-off Unknown

Damage Date	Damage Type	Severity
-------------	-------------	----------

04/15/2019	Collision	Unknown
------------	-----------	---------

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

 Service History Summary [Back To Top](#)

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

 Service History Summary Icon

Regular Oil Changes

- 4 oil services reported
- Last oil service reported **03/29/2021**

 Service History Summary Icon

Fluids Maintained

Information not available.

 Service History Summary Icon

Brakes Maintained

- 1 brake pad replacements
- Brake last maintained on **02/23/2016**

 Service History Summary Icon

Tires Maintained

Information not available.

 Service History Summary Icon

A/C & Climate Control

- 1 A/C services reported
- A/C system last serviced **06/18/2018**

 Service History Summary Icon

Other Services

- Cabin air filter replaced on **03/29/2021**
- Battery replaced on **03/29/2021**

OEM Recommended Services



Service History Summary Icon

120000 Mile Service

- Brake Fluid Exchange
- Check and correct all tires pressures including spare
- Check and correct brake fluid level



Service History Summary Icon

130000 Mile Service Not Yet Due

- Check and correct all tires pressures including spare
- Check and correct brake fluid level
- Check and record thickness of brake pads front & rear

[See more](#)

OEM Recommended Services



Please contact your local dealer or visit the OEM's website for details.



Service History Summary Icon

120000 Mile Service

- Brake Fluid Exchange
- Check and correct all tires pressures including spare
- Check and correct brake fluid level
- Check and record thickness of brake pads front & rear
- Check battery condition and provide print out
- Check headlamp settings correct if necessary
- Check horn
- Check interior/exterior lighting
- Check safety catch and hinges on hood for proper operation
- Check warning and indicator lamps
- Check windshield washer system for proper operation

- Clean visible area of water deflector
- Engine oil treatment
- ***FLEX B SERVICE***
- Inspect all steering components for signs of wear
- Inspect condition of poly v belt
- Inspect drive shaft flex discs
- Inspect front & rear axle ball joints for play and wear
- Inspect tires for damage and measure remaining tread life
- Perform Differential Service
- Perform GDI service
- Replace cabin dust filter
- Replace Engine Air Filter
- Replace engine oil and filter
- Reset Maintenance service indicator in instrument cluster
- Rotate tires (where applicable)



Service History Summary Icon

130000 Mile Service Not Yet Due

- Check and correct all tires pressures including spare
- Check and correct brake fluid level
- Check and record thickness of brake pads front & rear
- Check horn
- Check interior/exterior lighting
- Check safety catch and hinges on hood for proper operation
- Check warning and indicator lamps
- Clean visible area of water deflector
- Engine oil treatment
- ***FLEX A SERVICE***
- Inspect tires for damage and measure remaining tread life
- Perform GDI service

- Replace Engine Air Filter
- Replace engine oil and filter
- Reset Maintenance service indicator in instrument cluster

Close

 Odometer Dial Odometer Check [Back To Top](#)

 icon-success-pass

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

 icon-success-pass

State Title Odometer Check

No issues reported

 icon-success-pass

Auction Odometer Check

No issues reported

 icon-success-pass

Odometer Calculation Check

No issues reported

 Detailed Vehicle History Icon Detailed Vehicle History [Back To Top](#)

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2013 Mercedes-Benz E-Class E 350 (WDDKK5KF2DF207841) **Report Run Date:** 07/13/2026 14:41:03 EDT

2013

[Vehicle Prep and Other Pre-Titling Events](#)

Location: CA

Preparation Date: 03/2013

Event Date	Location	Odometer	Data Source	Details
03/14/2013	CA	29	Motor Vehicle Dept.	Odometer Reading from DMV

2013

[Owner 1](#)

Location: CA

Owned From: 03/2013

Usage: Lease

Event Date	Location	Odometer	Data Source	Details
03/22/2013	SAN CLEMENTE, CA		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)

Event Date	Location	Odometer	Data Source	Details
03/31/2013	CA		Motor Vehicle Dept.	Title(Lien Reported)
11/20/2015	LAGUNA NIGUEL, CA		Dealer Service	Multiple Point Vehicle Inspection Electrical System Serviced Tires or Wheels Service Performed Promotional Service Performed
12/28/2015	LAGUNA NIGUEL, CA		Dealer Service	Multiple Point Vehicle Inspection Tires or Wheels Service Performed Promotional Service Performed
02/22/2016	LAGUNA NIGUEL, CA		Dealer Service	Electrical System Serviced
02/23/2016	LAGUNA NIGUEL, CA		Dealer Service	Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Brakes Serviced Lights or Signals Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
02/25/2016	LAGUNA NIGUEL, CA		Dealer Service	Vehicle Serviced or Inspected
03/13/2016	CA	29,554	Motor Vehicle Dept.	Odometer Reading from DMV
03/28/2016	LAGUNA NIGUEL, CA		Dealer Service	Vehicle Serviced or Inspected

2016

[Owner 2](#)


Location: CA

Owned From: 04/2016

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
04/05/2016	WESTMINSTER, CA		Motor Vehicle Dept.	Title(Lien Reported) Registration Event/Renewal
10/17/2017	CA	47,098	Independent Repair Center	Fuel System Serviced Multiple Point Vehicle Inspection Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
06/18/2018	CA	53,193	Independent Repair Center	Cooling System Serviced Multiple Point Vehicle Inspection

Event Date	Location	Odometer	Data Source	Details
04/15/2019	COSTA MESA, CA		Damage Report	Tires or Wheels Service Performed Accident or Damage Reported Vehicle Damage Reported Left Side Damage or Repair Reported Right Side Damage or Repair Reported Rear Damage or Repair Reported Damage or Repair to Bumper Reported Damage or Repair to Wheels Reported Damage or Repair to Quarter Panel Reported
05/03/2019	CA		State Agency	Accident Reported, Event Date is Date Reported to AutoCheck
02/15/2020	CA	66,103	Service Record	Fuel System Serviced Vehicle Inspected Recommended Maintenance Performed Vehicle Detailed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
03/10/2021	CA	71,545	Motor Vehicle Dept.	Passed Emission Inspection
03/29/2021	WESTMINSTER, CA		Motor Vehicle Dept.	Title(Lien Reported)
03/29/2021	CA	71,920	Service Record	Vehicle Inspected Air Filter Changed Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
04/06/2021	WESTMINSTER, CA		Motor Vehicle Dept.	Registration Event/Renewal
10/03/2022	CORONA DEL MAR, CA		Motor Vehicle Dept.	Registration Event/Renewal



Event Date	Location	Odometer	Data Source	Details
03/28/2023	CA	91,564	Motor Vehicle Dept.	Passed Emission Inspection
03/28/2024	CA	100,527	Motor Vehicle Dept.	Passed Emission Inspection
03/20/2026	CA	120,368	Motor Vehicle Dept.	Passed Emission Inspection

2013

[Vehicle Prep and Other Pre-Titling Events](#)

Location: CA

Preparation Date: 03/2013

Event Date - 03/14/2013

Location - CA

Odometer - 29

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

2013

[Owner 1](#)

Location: CA

Owned From: 03/2013

Usage: Lease

Event Date - 03/22/2013

Location - SAN CLEMENTE, CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal(Leased Vehicle)

Event Date - 03/31/2013

Location - CA

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Event Date - 11/20/2015

Location - LAGUNA NIGUEL, CA

Data Source - Dealer Service

Details - Multiple Point Vehicle Inspection
Electrical System Serviced
Tires or Wheels Service Performed
Promotional Service Performed

Event Date - 12/28/2015

Location - LAGUNA NIGUEL, CA

Data Source - Dealer Service

Details - Multiple Point Vehicle Inspection
Tires or Wheels Service Performed
Promotional Service Performed

Event Date - 02/22/2016

Location - LAGUNA NIGUEL, CA

Data Source - Dealer Service

Details - Electrical System Serviced

Event Date - 02/23/2016

Location - LAGUNA NIGUEL, CA

Data Source - Dealer Service

Details - Battery Serviced or Replaced
Multiple Point Vehicle Inspection
Engine Serviced
Recommended Maintenance Performed
Brakes Serviced
Lights or Signals Serviced
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Promotional Service Performed

Event Date - 02/25/2016

Location - LAGUNA NIGUEL, CA

Data Source - Dealer Service

Details - Vehicle Serviced or Inspected

Event Date - 03/13/2016

Location - CA

Odometer - 29,554

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

Event Date - 03/28/2016

Location - LAGUNA NIGUEL, CA

Data Source - Dealer Service

Details - Vehicle Serviced or Inspected

2016

[Owner 2](#)

Location: CA

Owned From: 04/2016

Usage: Personal

Event Date - 04/05/2016

Location - WESTMINSTER, CA

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)
Registration Event/Renewal

Event Date - 10/17/2017

Location - CA

Odometer - 47,098

Data Source - Independent Repair Center

Details - Fuel System Serviced
Multiple Point Vehicle Inspection
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed

Event Date - 06/18/2018

Location - CA

Odometer - 53,193

Data Source - Independent Repair Center

Details - Cooling System Serviced
Multiple Point Vehicle Inspection

Tires or Wheels Service Performed

Event Date - 04/15/2019 dvh-timeline-icon-accident-orange.svg

Location - COSTA MESA, CA

Data Source - Damage Report

Details - Accident or Damage Reported
Vehicle Damage Reported
Left Side Damage or Repair Reported
Right Side Damage or Repair Reported
Rear Damage or Repair Reported
Damage or Repair to Bumper Reported
Damage or Repair to Wheels Reported
Damage or Repair to Quarter Panel Reported

Event Date - 05/03/2019

Location - CA

Data Source - State Agency

Details - Accident Reported, Event Date is Date Reported to AutoCheck

Event Date - 02/15/2020

Location - CA

Odometer - 66,103

Data Source - Service Record

Details - Fuel System Serviced
Vehicle Inspected
Recommended Maintenance Performed
Vehicle Detailed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed

Event Date - 03/10/2021

Location - CA

Odometer - 71,545

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 03/29/2021

Location - WESTMINSTER, CA

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Event Date - 03/29/2021

Location - CA

Odometer - 71,920

Data Source - Service Record

Details - Vehicle Inspected
Air Filter Changed
Battery Serviced or Replaced
Recommended Maintenance Performed
Vehicle Detailed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Promotional Service Performed

Event Date - 04/06/2021

Location - WESTMINSTER, CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 10/03/2022

Location - CORONA DEL MAR, CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 03/28/2023

Location - CA

Odometer - 91,564

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 03/28/2024

Location - CA

Odometer - 100,527

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 03/20/2026

Location - CA

Odometer - 120,368

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

 Warranty Check [Warranty Check](#) [Back To Top](#)

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Enter Mileage:

 miles

Show My Coverage

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-	 Expired	48 months / 50000 miles
Battery 	-	-	-	Contact a certified dealer to verify coverage
Corrosion 	-	-	 Expired	48 months / 50000 miles
Powertrain 	-	-	 Expired	48 months / 50000 miles
Roadside Assistance 	-	-	 Active	Unlimited months / Unlimited miles
Safety Restraint 	-	-	-	Contact a certified dealer to verify coverage

This Vehicle's Glossary [Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

- Term
- Section Location
- Definition
- State Title Brand
- Vehicle History at a Glance

A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

- Auction Issue
- Vehicle History at a Glance

This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

- Accident/Damage Check
- Vehicle History at a Glance

This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test

vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Insurance Loss/Title Transfer

Vehicle History at a Glance

This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Additional History

Vehicle History at a Glance

This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Odometer Check

Vehicle History at a Glance

This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Loan/Lien

Additional History

A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Lease Use

Owner Type

Vehicle was registered as lease vehicle.

Accident

Accident / Damage

A state or municipality has reported an accident or collision for this vehicle that may or may not have sustained damage. Not all damage events are reported to AutoCheck and the damage severity of reported events will vary. In all events AutoCheck recommends that prospective vehicle purchasers conduct a detailed vehicle inspection prior to purchase of a pre-owned vehicle.

Term - State Title Brand

Section Location - Vehicle History at a Glance

Definition - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Term - Auction Issue

Section Location - Vehicle History at a Glance

Definition - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Accident/Damage Check

Section Location - Vehicle History at a Glance

Definition - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Term - Insurance Loss/Title Transfer

Section Location - Vehicle History at a Glance

Definition - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Term - Additional History

Section Location - Vehicle History at a Glance

Definition - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Term - Odometer Check

Section Location - Vehicle History at a Glance

Definition - This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Term - Loan/Lien

Section Location - Additional History

Definition - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Term - Lease Use

Section Location - Owner Type

Definition - Vehicle was registered as lease vehicle.

Term - Accident

Section Location - Accident / Damage

Definition - A state or municipality has reported an accident or collision for this vehicle that may or may not have sustained damage. Not all damage events are reported to AutoCheck and the damage severity of reported events will vary. In all events AutoCheck recommends that prospective vehicle purchasers conduct a detailed vehicle inspection prior to purchase of a pre-owned vehicle.