

Print Report



## Experian AutoCheck Report

Report run: 06/30/2026 21:34:40 EDT

### 2012 Chevrolet Cruze LT

Sedan 4D (1.4L I4 SMPI Gasoline)

VIN: 1G1PF5SC4C7285274

Class: Car - Midsize

Country of Assembly: United States

Vehicle Age: 14 year(s)

Estimated In Service: 07/10/2012

Last Reported Odometer: 155,078 (06/05/2026)

[View Vehicle Label](#)



Vehicle Usage  
Personal

## Vehicle History at a Glance



State Title Brand



Clean



Auction Brand / Issues




No Issue



**Accident / Damage**  
No Accidents or Damage Reported



No Issue



**Open Recall Check**



No Open Recalls



**Insurance Loss / Transfer**



No Issue



**Odometer Check**  
Last reported odometer:  
155,078 (06/05/2026)



No Issue



**Certified Pre-Owned**



No CPO Info Available



### Service / Repair

20 Service Record(s) Reported



No Issue



### Additional History

Lien Reported, Corrected Title



Events Reported



### This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

[Learn More](#)




## Accident & Damage

[Back To Top](#)

### Your Vehicle Checks Out

There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



No Damage

## Service History

[Back To Top](#)

### Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.



#### Regular Oil Changes

- 3 oil services reported
- Last oil service reported **01/10/2023**



#### Fluids Maintained

- 1 coolant flushes
- Last fluid maintained **01/12/2023**



#### Brakes Maintained

- 2 brake pad replacements
- Brake last maintained on **09/06/2022**



#### Tires Maintained

Information not available.



#### A/C & Climate Control

- 4 A/C services reported
- A/C system last serviced **01/10/2023**



#### Other Services

- Cabin air filter replaced on **01/12/2023**
- Battery replaced on **05/24/2021**

### OEM Recommended Services



### 150000 Mile Service

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function

[See more](#)



## Odometer Check

[Back To Top](#)



### Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



#### State Title Odometer Check

No issues reported



#### Auction Odometer Check

No issues reported



#### Odometer Calculation Check

No issues reported

Below are the historical events for this vehicle listed in chronological order.

**Vehicle:** 2012 Chevrolet Cruze LT (1G1PF5SC4C7285274) **Report Run Date:** 06/30/2026 21:34:40 EDT

2012

## Owner 1

**Location:** OH

**Owned From:** 07/2012

**Usage:** Personal

Event Date - 07/10/2012

Location - WESTLAKE, OH

Odometer - 16

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Event Date - 07/19/2012

Location - WESTLAKE, OH

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 09/06/2012

Location - REDMOND, WA

Odometer - 12,007

Data Source - Motor Vehicle Dept.

[Details](#) - Title(Lien Reported)  
Registration Event/Renewal

[Event Date](#) - 08/02/2013

[Location](#) - REDMOND, WA

[Odometer](#) - 20,865

[Data Source](#) - Independent Repair Center

[Details](#) - Vehicle Serviced or Inspected

[Event Date](#) - 08/05/2013

[Location](#) - SEATTLE, WA

[Data Source](#) - Motor Vehicle Dept.

[Details](#) - Registration Event/Renewal

[Event Date](#) - 08/25/2014

[Location](#) - SEATTLE, WA

[Data Source](#) - Motor Vehicle Dept.

[Details](#) - Registration Event/Renewal

[Event Date](#) - 07/16/2015

[Location](#) - MONROE, WA

[Data Source](#) - Motor Vehicle Dept.

[Details](#) - Registration Event/Renewal

[Event Date](#) - 07/14/2016

[Location](#) - MONROE, WA

[Data Source](#) - Motor Vehicle Dept.

[Details](#) - Registration Event/Renewal

[Event Date](#) - 06/05/2017

[Location](#) - KIRKLAND, WA

[Odometer](#) - 94,350

[Data Source](#) - Service Record

[Details](#) - Cooling System Serviced

[Event Date](#) - 06/05/2017

[Location](#) - KIRKLAND, WA

[Data Source](#) - Service Record

[Details](#) - Fuel System Serviced

Air Filter Changed

Multiple Point Vehicle Inspection

Engine Serviced

Transmission Serviced

Brakes Serviced

[Event Date](#) - 08/24/2017

[Location](#) - MONROE, WA

[Data Source](#) - Motor Vehicle Dept.

[Details](#) - Registration Event/Renewal

[Event Date](#) - 11/14/2017

[Location](#) - KIRKLAND, WA

[Odometer](#) - 103,233

[Data Source](#) - Service Record

[Details](#) - Fuel System Serviced

[Event Date](#) - 11/14/2017

[Location](#) - KIRKLAND, WA

[Data Source](#) - Service Record

[Details](#) - Multiple Point Vehicle Inspection

Engine Serviced

Recommended Maintenance Performed

Lights or Signals Serviced

Event Date - 12/21/2017

Location - KIRKLAND, WA

Odometer - 104,958

Data Source - Service Record

Details - Fuel System Serviced

Event Date - 12/21/2017

Location - KIRKLAND, WA

Data Source - Service Record

Details - Battery Serviced or Replaced  
Multiple Point Vehicle Inspection  
Engine Serviced  
Recommended Maintenance Performed

Event Date - 08/24/2018

Location - MONROE, WA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 03/25/2019

Location - KIRKLAND, WA

Odometer - 126,454

Data Source - Service Record

Details - Cooling System Serviced

Event Date - 03/25/2019

Location - KIRKLAND, WA

Data Source - Service Record

Details - Heat or Air Conditioning Serviced  
Multiple Point Vehicle Inspection  
Engine Serviced  
Recommended Maintenance Performed

Transmission Serviced  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed

Event Date - 03/29/2019

Location - WA

Data Source - Service Record

Details - Vehicle Inspected  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed  
Promotional Service Performed

Event Date - 07/15/2019

Location - MONROE, WA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 08/04/2020

Location - MONROE, WA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/30/2021

Location - KIRKLAND, WA

Odometer - 141,253

Data Source - Service Record

Details - Cooling System Serviced

Event Date - 04/30/2021

Location - KIRKLAND, WA

Data Source - Service Record

[Details](#) - Multiple Point Vehicle Inspection  
Engine Serviced  
Recommended Maintenance Performed  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed

[Event Date](#) - 05/24/2021

[Location](#) - KIRKLAND, WA

[Odometer](#) - 141,533

[Data Source](#) - Service Record

[Details](#) - Air Filter Changed

[Event Date](#) - 05/24/2021

[Location](#) - KIRKLAND, WA

[Data Source](#) - Service Record

[Details](#) - Battery Serviced or Replaced  
Multiple Point Vehicle Inspection  
Engine Serviced  
Recommended Maintenance Performed  
Wipers Replaced And/Or Serviced  
Tires or Wheels Service Performed

[Event Date](#) - 08/02/2021

[Location](#) - MONROE, WA

[Data Source](#) - Motor Vehicle Dept.

[Details](#) - Registration Event/Renewal

[Event Date](#) - 08/24/2022

[Location](#) - MONROE, WA

[Data Source](#) - Motor Vehicle Dept.

[Details](#) - Registration Event/Renewal

[Event Date](#) - 09/01/2022

[Location](#) - KIRKLAND, WA

Odometer - 152,757

Data Source - Service Record

Details - Multiple Point Vehicle Inspection

Event Date - 09/01/2022

Location - KIRKLAND, WA

Data Source - Service Record

Details - Engine Serviced

Brakes Serviced

Starting or Charging System Service Performed

Event Date - 09/06/2022

Location - WA

Data Source - Service Record

Details - Vehicle Inspected

Brakes Serviced

Promotional Service Performed

Event Date - 01/10/2023

Location - KIRKLAND, WA

Odometer - 154,949

Data Source - Service Record

Details - Cooling System Serviced

Event Date - 01/10/2023

Location - KIRKLAND, WA

Data Source - Service Record

Details - Air Filter Changed

Multiple Point Vehicle Inspection

Engine Serviced

Wipers Replaced And/Or Serviced

Exhaust System Serviced

Drive Line Serviced

Electrical System Serviced  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed

**Event Date** - 01/12/2023

**Location** - WA

**Data Source** - Service Record

**Details** - Vehicle Inspected  
Air Filter Changed  
Wipers Replaced And/Or Serviced  
Lights or Signals Serviced  
Tires or Wheels Service Performed  
Vehicle Fluids Serviced

**Event Date** - 07/31/2023

**Location** - MONROE, WA

**Data Source** - Motor Vehicle Dept.

**Details** - Registration Event/Renewal

**Event Date** - 05/11/2026

**Location** - WESTLAKE, OH

**Data Source** - Motor Vehicle Dept.

**Details** - Title(Lien Reported)  
Corrected Title(Lien Reported)

**Event Date** - 06/05/2026

**Location** - PACIFIC NW REGION

**Odometer** - 155,078

**Data Source** - Auto Auction

**Details** - Reported at Auto Auction

---






# Warranty Check

[Back To Top](#)

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Enter Mileage:

 miles[Show My Coverage](#)

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-		<b>36 months / 36000 miles</b>
Battery 	-	-	-	<b>Contact a certified dealer to verify coverage</b>
Corrosion 	-	-		<b>72 months / 100000 miles</b> Rust-through coverage only, Corrosion coverage is for the first 3 years or 36,000 miles
Powertrain 	-	-		<b>60 months / 100000 miles</b>
Roadside Assistance 	-	-		<b>60 months / 100000 miles</b>
Safety Restraint 	-	-	-	<b>Contact a certified dealer to verify coverage</b>

## This Vehicle's Glossary

[Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

[Term - State Title Brand](#)

[Section Location - Vehicle History at a Glance](#)

**Definition** - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

[Term - Auction Issue](#)

[Section Location - Vehicle History at a Glance](#)

### **AutoCheck Terms and Conditions**

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at [www.autocheck.com/terms](http://www.autocheck.com/terms) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

### **About AutoCheck**

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

### **Patent Notice**

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.