

Experian AutoCheck Report

Report run: 07/06/2026 18:40:07 EDT
2010 Toyota Prius I / II / III / IV / V
Hatchback 4D (1.8L I4 SMPI Gas/Electric Hybrid)
VIN:
JTDDKN3DU6A0160748
Class:
Car - Midsize
Country of Assembly:
Japan
Vehicle Age:
16 year(s)
Estimated In Service:
04/20/2010
Last Reported Odometer:
149,296 (05/01/2026)
Owners - 2
 Number of Owners
Vehicle Usage
Personal
x

Window Sticker

Loading window sticker...



Download PDF

Vehicle History at a Glance

 vhg-title-brand-no-issue

State Title Brand

 icon-success-pass

Clean

 auction brand icon

Auction Brand / Issues

 icon-success-pass

No Issue

 vhg-accident-damage-issue-found

Accident / Damage

 icon-warning

Minor

 recall check icon

Open Recall Check

 icon-success-pass
No Open Recalls
 vhg-insurance-loss-title-no-issue

Insurance Loss / Transfer

 icon-success-pass
No Issue
 vhg-odometer-check-no-issue

Odometer Check

Last reported odometer:
149,296 (05/01/2026)

 icon-success-pass
No Issue
 cpo icon

Certified Pre-Owned

 icon-success-pass
No CPO Info Available
 service repair icon

Service / Repair

16 Service Record(s) Reported

 icon-success-pass
No Issue
 vhg-additional-history-issue-found

Additional History

Lien Reported

 icon-more-information
Events Reported
 vhg-title-brand-no-issue

This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

[Learn More](#)

-  damage icon Accident & Damage [Back To Top](#)
-  accident-car-no-poi-available
-  accident-airbag-deployed-off Airbag Deployed
-  accident-structural-damage-off Structural Damage
-  accident-overturned-off Overturned
-  accident-severe-on Minor

Damage Date Damage Type Severity

04/30/2019 Collision Minor

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

Service History Summary Icon Service History [Back To Top](#)

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

Service History Summary Icon

Regular Oil Changes

- **11** oil services reported
- Last oil service reported **05/01/2026**

Service History Summary Icon

Fluids Maintained

- **1** coolant flushes
- Last fluid maintained **10/25/2022**

Service History Summary Icon

Brakes Maintained

- **2** brake pad replacements
- Brake last maintained on **02/21/2024**

Service History Summary Icon

Tires Maintained

Information not available.

Service History Summary Icon

A/C & Climate Control

- **1** A/C services reported
- A/C system last serviced **10/25/2022**

Service History Summary Icon

Other Services

- Cabin air filter replaced on **07/03/2025**
- Battery replaced on **05/01/2026**

OEM Recommended Services

Service History Summary Icon

120000 Mile Service

- Check installation of driver's floor mat
- Four Wheel Alignment
- Fuel Induction Service

[See more](#)

OEM Recommended Services



Please contact your local dealer or visit the OEM's website for details.



Service History Summary Icon

120000 Mile Service

- Check installation of driver's floor mat
- Four Wheel Alignment
- Fuel Induction Service
- Inspect and adjust all fluid levels
- Inspect automatic transmission fluid
- Inspect ball joints and dust covers
- Inspect brake lines and hoses
- Inspect brake linings/drums and brake pads/discs
- Inspect drive shaft boots
- Inspect engine/inverter coolant
- Inspect exhaust pipes and mountings
- Inspect front differential oil
- Inspect fuel lines and connections, fuel tank band and fuel tank vapor vent system hoses
- Inspect fuel tank cap gasket
- Inspect radiator, condenser and/or intercooler
- Inspect steering gear box
- Inspect steering linkage and boots
- Replace automatic transmission fluid
- Replace brake fluid

- Replace cabin air filter (except solar power ventilation system)
- Replace engine air filter
- Replace engine coolant
- Replace engine oil and oil filter (0W-20)
- Replace spark plugs
- Rotate tires
- Visually inspect brake linings/drums and brake pads/discs
- Wiper Blade Replacement (Front)

Close

 Odometer Dial Odometer Check [Back To Top](#)

 icon-success-pass

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

 icon-success-pass

State Title Odometer Check

No issues reported

 icon-success-pass

Auction Odometer Check

No issues reported

 icon-success-pass

Odometer Calculation Check

No issues reported

 Detailed Vehicle History Icon Detailed Vehicle History [Back To Top](#)

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2010 Toyota Prius I / II / III / IV / V (JTDKN3DU6A0160748) **Report Run Date:** 07/06/2026 18:40:07 EDT

2010

[Vehicle Prep and Other Pre-Titling Events](#)

Preparation Date: 04/2010

Event Date	Location	Odometer	Data Source	Details
04/20/2010			Independent Source	Vehicle Manufactured and Shipped to Dealer
04/20/2010	OR		Independent Source	Vehicle Manufactured and Shipped to Dealer
06/28/2010	OR	127	Motor Vehicle Dept.	Odometer Reading from DMV

2010

[Owner 1](#)

Location: OR
Owned From: 07/2010
Usage: Personal


Event Date	Location	Odometer	Data Source	Details
07/15/2010	BONANZA, OR		Motor Vehicle Dept.	Title(Lien Reported) Registration Event/Renewal
11/02/2012	BONANZA, OR		Motor Vehicle Dept.	Registration Event/Renewal
11/07/2012	BONANZA, OR		Motor Vehicle Dept.	Registration Event/Renewal
06/05/2013	OR	38,000	State Agency	Passed Emission Inspection
06/15/2013	OR	38,102	Motor Vehicle Dept.	Odometer Reading from DMV
07/05/2013	OR	39,000	State Agency	Passed Emission Inspection

2013

[Owner 2](#)

Location: OR
Owned From: 07/2013
Usage: Personal

Event Date	Location	Odometer	Data Source	Details
07/19/2013	MEDFORD, OR		Motor Vehicle Dept.	Title
07/19/2013	MEDFORD, OR		Motor Vehicle Dept.	Registration Event/Renewal
04/17/2015	OR	56,000	State Agency	Passed Emission Inspection
04/28/2015	MEDFORD, OR		Motor Vehicle Dept.	Registration Event/Renewal
04/14/2017	OR		State Agency	Passed Emission Inspection
04/25/2017	MEDFORD, OR		Motor Vehicle Dept.	Registration Event/Renewal
03/07/2019	OR	96,331	Service Record	Vehicle Serviced or Inspected
04/29/2019	MEDFORD, OR		Motor Vehicle Dept.	Registration Event/Renewal
04/29/2019	OR	99,110	State Agency	Passed Emission Inspection
04/30/2019	MEDFORD, OR	99,117	Damage Report	Accident or Collision Reported Minor Damage Reported Body Repair Performed
06/15/2019	OR	101,593	Service Record	Vehicle Inspected Battery Serviced or Replaced



Event Date	Location	Odometer	Data Source	Details
12/17/2019 OR		108,302	Service Record	Recommended Maintenance Performed Vehicle Detailed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
				Vehicle Inspected Air Filter Changed Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed Wipers Replaced And/Or Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
				Vehicle Inspected Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
09/15/2020 OR		113,581	Service Record	Vehicle Inspected Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
				Vehicle Inspected Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed Brakes Serviced Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
				Vehicle Inspected Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed Brakes Serviced Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
03/17/2021 OR		118,405	Service Record	Vehicle Inspected Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed Brakes Serviced Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
				Vehicle Inspected Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed Brakes Serviced Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed
				Vehicle Inspected Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed Brakes Serviced Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed

Event Date	Location	Odometer	Data Source	Details
05/06/2021	MEDFORD, OR		Motor Vehicle Dept.	Registration Event/Renewal
05/06/2021	OR	119,805	Motor Vehicle Dept.	Passed Emission Inspection Vehicle Inspected Battery Serviced or Replaced Recommended Maintenance Performed Vehicle Detailed
02/08/2022	OR	123,017	Service Record	Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed Cooling System Serviced Fuel System Serviced Air Filter Changed Battery Serviced or Replaced Multiple Point Vehicle Inspection Accessories Serviced or Installed Recommended Maintenance Performed Vehicle Detailed
10/25/2022	MEDFORD, OR	127,582	Lithia Toyota Scion 541.618.4800	Transmission Serviced Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Body Service Performed Vehicle Fluids Serviced Promotional Service Performed
05/08/2023	MEDFORD, OR		Motor Vehicle Dept.	Registration Event/Renewal
05/08/2023	OR	130,255	Motor Vehicle Dept.	Passed Emission Inspection
06/06/2023	OR	130,999	Service Record	Vehicle Inspected
06/06/2023	MEDFORD, OR	130,999	Lithia Toyota Scion 541.618.4800	Battery Serviced or Replaced Multiple Point Vehicle Inspection Recommended Maintenance Performed Vehicle Detailed

Event Date	Location	Odometer	Data Source	Details
02/21/2024	OR	135,799	Service Record	Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Body Service Performed Promotional Service Performed Vehicle Inspected Air Filter Changed Battery Serviced or Replaced Multiple Point Vehicle Inspection Recommended Maintenance Performed Vehicle Detailed Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Body Service Performed Promotional Service Performed
02/21/2024	MEDFORD, OR	135,799	Lithia Toyota Scion 541.618.4800	
11/04/2024	OR	139,771	Service Record	Vehicle Inspected Battery Serviced or Replaced Multiple Point Vehicle Inspection Recommended Maintenance Performed Vehicle Detailed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Body Service Performed Promotional Service Performed
11/04/2024	MEDFORD, OR	139,771	Lithia Toyota Scion 541.618.4800	
04/30/2025	MEDFORD, OR		Motor Vehicle Dept.	Registration Event/Renewal
04/30/2025	OR	143,092	Motor Vehicle Dept.	Passed Emission Inspection
07/03/2025	OR	144,394	Service Record	Vehicle Inspected
07/03/2025		144,394	Lithia Toyota Scion 541.618.4800	Air Filter Changed Battery Serviced or Replaced Multiple Point Vehicle Inspection Recommended Maintenance Performed

Event Date	Location	Odometer	Data Source	Details
				Vehicle Detailed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Body Service Performed Promotional Service Performed Vehicle Inspected Battery Serviced or Replaced Recommended Maintenance Performed
05/01/2026	OR	149,296	Service Record	Vehicle Detailed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Promotional Service Performed

2010

[Vehicle Prep and Other Pre-Titling Events](#)

Preparation Date: 04/2010

Event Date - 04/20/2010

Location -

Data Source - Independent Source

Details - Vehicle Manufactured and Shipped to Dealer

Event Date - 04/20/2010

Location - OR

Data Source - Independent Source

Details - Vehicle Manufactured and Shipped to Dealer

Event Date - 06/28/2010

Location - OR

Odometer - 127

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

2010

[Owner 1](#)

Location: OR

Owned From: 07/2010

Usage: Personal

Event Date - 07/15/2010

Location - BONANZA, OR

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)
Registration Event/Renewal

Event Date - 11/02/2012

Location - BONANZA, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 11/07/2012

Location - BONANZA, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 06/05/2013

Location - OR

Odometer - 38,000

Data Source - State Agency

Details - Passed Emission Inspection

Event Date - 06/15/2013

Location - OR

Odometer - 38,102

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

Event Date - 07/05/2013

Location - OR

Odometer - 39,000

Data Source - State Agency

Details - Passed Emission Inspection

2013

[Owner 2](#)

Location: OR

Owned From: 07/2013

Usage: Personal

Event Date - 07/19/2013

Location - MEDFORD, OR

Data Source - Motor Vehicle Dept.

Details - Title

Event Date - 07/19/2013

Location - MEDFORD, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/17/2015

Location - OR

Odometer - 56,000

Data Source - State Agency

Details - Passed Emission Inspection

Event Date - 04/28/2015

Location - MEDFORD, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/14/2017

Location - OR

Data Source - State Agency

Details - Passed Emission Inspection

Event Date - 04/25/2017

Location - MEDFORD, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 03/07/2019

Location - OR

Odometer - 96,331

Data Source - Service Record

Details - Vehicle Serviced or Inspected

Event Date - 04/29/2019

Location - MEDFORD, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/29/2019

Location - OR

Odometer - 99,110

Data Source - State Agency

Details - Passed Emission Inspection

Event Date - 04/30/2019  dvh-timeline-icon-accident-orange.svg

Location - MEDFORD, OR

Odometer - 99,117

Data Source - Damage Report

Details - Accident or Collision Reported

Minor Damage Reported

Body Repair Performed

Event Date - 06/15/2019

Location - OR

Odometer - 101,593

Data Source - Service Record

Details - Vehicle Inspected
Battery Serviced or Replaced
Recommended Maintenance Performed
Vehicle Detailed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Promotional Service Performed

Event Date - 12/17/2019

Location - OR

Odometer - 108,302

Data Source - Service Record

Details - Vehicle Inspected
Air Filter Changed
Battery Serviced or Replaced
Recommended Maintenance Performed
Vehicle Detailed
Wipers Replaced And/Or Serviced
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Promotional Service Performed

Event Date - 09/15/2020

Location - OR

Odometer - 113,581

Data Source - Service Record

Details - Vehicle Inspected
Battery Serviced or Replaced
Recommended Maintenance Performed
Vehicle Detailed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Promotional Service Performed

Event Date - 03/17/2021

Location - OR

Odometer - 118,405

Data Source - Service Record

Details - Vehicle Inspected
Battery Serviced or Replaced
Recommended Maintenance Performed

Vehicle Detailed
Brakes Serviced
Electrical System Serviced
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Promotional Service Performed

Event Date - 05/06/2021

Location - MEDFORD, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 05/06/2021

Location - OR

Odometer - 119,805

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 02/08/2022

Location - OR

Odometer - 123,017

Data Source - Service Record

Details - Vehicle Inspected
Battery Serviced or Replaced
Recommended Maintenance Performed
Vehicle Detailed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Promotional Service Performed

Event Date - 10/25/2022

Location - MEDFORD, OR

Odometer - 127,582

Data Source - [Lithia Toyota Scion](#) 541.618.4800

Details - Cooling System Serviced
Fuel System Serviced
Air Filter Changed
Battery Serviced or Replaced
Multiple Point Vehicle Inspection
Accessories Serviced or Installed
Recommended Maintenance Performed
Vehicle Detailed

Transmission Serviced
Electrical System Serviced
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Body Service Performed
Vehicle Fluids Serviced
Promotional Service Performed

Event Date - 05/08/2023

Location - MEDFORD, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 05/08/2023

Location - OR

Odometer - 130,255

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 06/06/2023

Location - OR

Odometer - 130,999

Data Source - Service Record

Details - Vehicle Inspected

Event Date - 06/06/2023

Location - MEDFORD, OR

Odometer - 130,999

Data Source - [Lithia Toyota Scion](#) 541.618.4800

Details - Battery Serviced or Replaced
Multiple Point Vehicle Inspection
Recommended Maintenance Performed
Vehicle Detailed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Body Service Performed
Promotional Service Performed

Event Date - 02/21/2024

Location - OR

Odometer - 135,799

Data Source - Service Record

Details - Vehicle Inspected

Event Date - 02/21/2024

Location - MEDFORD, OR

Odometer - 135,799

Data Source - [Lithia Toyota Scion](#) 541.618.4800

Details - Air Filter Changed
Battery Serviced or Replaced
Multiple Point Vehicle Inspection
Recommended Maintenance Performed
Vehicle Detailed
Brakes Serviced
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Body Service Performed
Promotional Service Performed

Event Date - 11/04/2024

Location - OR

Odometer - 139,771

Data Source - Service Record

Details - Vehicle Inspected

Event Date - 11/04/2024

Location - MEDFORD, OR

Odometer - 139,771

Data Source - [Lithia Toyota Scion](#) 541.618.4800

Details - Battery Serviced or Replaced
Multiple Point Vehicle Inspection
Recommended Maintenance Performed
Vehicle Detailed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Body Service Performed
Promotional Service Performed

Event Date - 04/30/2025

Location - MEDFORD, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/30/2025

Location - OR

Odometer - 143,092

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 07/03/2025

Location - OR

Odometer - 144,394

Data Source - Service Record

Details - Vehicle Inspected

Event Date - 07/03/2025

Location -

Odometer - 144,394

Data Source - [Lithia Toyota Scion](#) 541.618.4800

Details - Air Filter Changed
Battery Serviced or Replaced
Multiple Point Vehicle Inspection
Recommended Maintenance Performed
Vehicle Detailed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Body Service Performed
Promotional Service Performed

Event Date - 05/01/2026

Location - OR

Odometer - 149,296

Data Source - Service Record

Details - Vehicle Inspected
Battery Serviced or Replaced
Recommended Maintenance Performed
Vehicle Detailed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Promotional Service Performed

This Vehicle's Glossary[Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

Term
Section Location
Definition
State Title Brand

Vehicle History at a Glance

A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Auction Issue

Vehicle History at a Glance

This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Accident/Damage Check

Vehicle History at a Glance

This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Insurance Loss/Title Transfer

Vehicle History at a Glance

This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Additional History

Vehicle History at a Glance

This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Odometer Check

Vehicle History at a Glance

This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Loan/Lien

Additional History

A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Personal Use

Owner Type

This vehicle was driven for personal use.

Accident

Accident / Damage

A state or municipality has reported an accident or collision for this vehicle that may or may not have sustained damage. Not all damage events are reported to AutoCheck and the damage severity of reported events will vary. In all events AutoCheck recommends that prospective vehicle purchasers conduct a detailed vehicle inspection prior to purchase of a pre-owned vehicle.

Term - State Title Brand

Section Location - Vehicle History at a Glance

Definition - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Term - Auction Issue

Section Location - Vehicle History at a Glance

Definition - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Accident/Damage Check

Section Location - Vehicle History at a Glance

Definition - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Term - Insurance Loss/Title Transfer

Section Location - Vehicle History at a Glance

Definition - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Term - Additional History

Section Location - Vehicle History at a Glance

Definition - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Term - Odometer Check

Section Location - Vehicle History at a Glance

Definition - This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Term - Loan/Lien

Section Location - Additional History

Definition - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Term - Personal Use

Section Location - Owner Type

Definition - This vehicle was driven for personal use.

Term - Accident

Section Location - Accident / Damage

Definition - A state or municipality has reported an accident or collision for this vehicle that may or may not have sustained damage. Not all damage events are reported to AutoCheck and the damage severity of reported events will vary. In all events AutoCheck recommends that prospective vehicle purchasers conduct a detailed vehicle inspection prior to purchase of a pre-owned vehicle.