

Print Report



# Experian AutoCheck Report

Report run: 06/15/2026 14:37:43 EDT  
2016 Honda Civic EX-L / EX-L w/Navi  
Sedan 4D (1.5L I4 DI Gasoline)

VIN:  
2HGFC1F75GH639364

Class:  
Car - Midsize  
Country of Assembly:  
Canada

Vehicle Age:  
10 year(s)  
Estimated In Service:  
03/22/2016

Last Reported Odometer:  
102,280 (02/18/2026)

[View Vehicle Label](#)

Number of Owners  
Vehicle Usage  
Personal  
x

## Window Sticker

Loading window sticker...



[Download PDF](#)

Vehicle History at a Glance  
 vhg-title-brand-no-issue

State Title Brand

icon-success-pass  
Clean  
 auction brand icon

Auction Brand / Issues


icon-success-pass  
No Issue  
 vhg-accident-damage-no-issue

Accident / Damage


No Accidents or Damage Reported

icon-success-pass


No Issue

 recall check icon


Open Recall Check

 icon-success-pass


No Open Recalls

 vhg-insurance-loss-title-no-issue

Insurance Loss / Transfer

 icon-success-pass


No Issue

 vhg-odometer-check-no-issue


Odometer Check

Last reported odometer:


102,280 (02/18/2026)

 icon-success-pass


No Issue

 cpo icon

Certified Pre-Owned

 icon-success-pass

No CPO Info Available


 service repair icon

Service / Repair

12 Service Record(s) Reported


 icon-success-pass

No Issue

 vhg-additional-history-issue-found

Additional History

Lien Reported

 icon-more-information

Events Reported


 vhg-title-brand-no-issue


## This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

[Learn More](#)

 damage icon Accident & Damage [Back To Top](#)

 accident-car-outline-no-impact

 accident-airbag-deployed-off Airbag Deployed

 accident-structural-damage-off Structural Damage

 accident-overturned-off Overturned

## accident-severe-off No Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.

 Service History Summary Icon [Back To Top](#)

## Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

## Service History Summary Icon

### Regular Oil Changes

- **8** oil services reported
- Last oil service reported **03/09/2023**

## Service History Summary Icon

### Fluids Maintained

- **2** coolant flushes
- Last fluid maintained **06/11/2018**

## Service History Summary Icon

### Brakes Maintained

- **4** brake pad replacements
- Brake last maintained on **08/17/2021**

## Service History Summary Icon

### Tires Maintained

Information not available.

## Service History Summary Icon

### A/C & Climate Control

- **4** A/C services reported
- A/C system last serviced **03/09/2023**

## Service History Summary Icon

### Other Services

- Cabin air filter replaced on **08/17/2021**
- Battery replaced on **12/27/2021**

## OEM Recommended Services

## Service History Summary Icon

### 100000 Mile Service

- Adjust parking brake (if applicable)
- Adjust Tire Pressure
- Alignment

## Service History Summary Icon

### 105000 Mile Service Not Yet Due

- Adjust parking brake (if applicable)
- Adjust Tire Pressure
- Alignment

[See more](#)

### OEM Recommended Services



Please contact your local dealer or visit the OEM's website for details.

## Service History Summary Icon

### 100000 Mile Service

- Adjust parking brake (if applicable)
- Adjust Tire Pressure
- Alignment
- Engine Oil & Filter Change
- Genuine Honda Cabin Air Filter Installed
- Honda Factory Multi-Point Inspection
- Inspect Brake Wear
- Inspect Tire Condition & Tread Wear
- Perform a Battery Health Check
- Replace Engine Air Filter
- Replace Intelligent Key Remote Battery
- Reset Maintenance Indicator

- Road Test Vehicle
- Rotate & Balance Tires
- Rotate Tires


### Service History Summary Icon

#### 105000 Mile Service Not Yet Due

- Adjust parking brake (if applicable)
- Adjust Tire Pressure
- Alignment
- Engine Oil & Filter Change
- Genuine Honda Cabin Air Filter Installed
- Honda Factory Multi-Point Inspection
- Inspect Brake Wear
- Inspect Tire Condition & Tread Wear
- Perform a Battery Health Check
- Replace Engine Air Filter
- Replace Intelligent Key Remote Battery
- Reset Maintenance Indicator
- Road Test Vehicle
- Rotate & Balance Tires
- Rotate Tires


Close

### Odometer Dial Odometer Check [Back To Top](#)

 icon-success-pass

#### Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

 icon-success-pass


#### State Title Odometer Check

No issues reported

 icon-success-pass

#### Auction Odometer Check

No issues reported

 icon-success-pass  
Odometer Calculation Check

No issues reported

 Detailed Vehicle History Icon Detailed Vehicle History [Back To Top](#)

Below are the historical events for this vehicle listed in chronological order.

**Vehicle:** 2016 Honda Civic EX-L / EX-L w/Navi (2HGFC1F75GH639364) **Report Run Date:** 06/15/2026 14:37:43 EDT

2016

[Vehicle Prep and Other Pre-Titling Events](#)

**Location:** OR

**Preparation Date:** 03/2016

| Event Date | Location | Odometer | Data Source         | Details                   |
|------------|----------|----------|---------------------|---------------------------|
| 03/22/2016 | OR       | 30       | Motor Vehicle Dept. | Odometer Reading from DMV |

2016

[Owner 1](#)

**Location:** OR

**Owned From:** 04/2016

**Usage:** Personal

| Event Date | Location    | Odometer | Data Source         | Details  |
|------------|-------------|----------|---------------------|--|
| 04/27/2016 | CORBETT, OR |          | Motor Vehicle Dept. | Title(Lien Reported)<br>Registration Event/Renewal   |
| 05/06/2016 | CORBETT, OR |          | Motor Vehicle Dept. | Title(Lien Reported)<br>Registration Event/Renewal<br>Multiple Point Vehicle Inspection<br>Engine Serviced<br>Recommended Maintenance Performed  |
| 04/07/2017 |             | 16,722   | Service Record      | Wipers Replaced And/Or Serviced<br>Brakes Serviced<br>Lights or Signals Serviced<br>Tires or Wheels Service Performed<br>Lube, Oil And/Or Filter Changed<br>Air Filter Changed<br>Multiple Point Vehicle Inspection<br>Engine Serviced |
| 11/21/2017 |             | 25,836   | Service Record      | Recommended Maintenance Performed<br>Tires or Wheels Service Performed<br>Lube, Oil And/Or Filter Changed<br>Vehicle Fluids Serviced   |
| 06/11/2018 |             | 34,968   | Service Record      | Multiple Point Vehicle Inspection<br>Engine Serviced<br>Recommended Maintenance Performed<br>Brakes Serviced   |

| Event Date | Location         | Odometer | Data Source            | Details   |
|------------|------------------|----------|------------------------|---|
| 12/11/2018 |                  | 41,949   | Service Record         | Tires or Wheels Service Performed<br>Lube, Oil And/Or Filter Changed<br>Vehicle Fluids Serviced   |
| 03/20/2019 |                  | 45,450   | Service Record         | Tires or Wheels Service Performed<br>Heat or Air Conditioning Serviced<br>Air Filter Changed<br>Multiple Point Vehicle Inspection<br>Engine Serviced<br>Recommended Maintenance Performed<br>Tires or Wheels Service Performed<br>Lube, Oil And/Or Filter Changed |
| 08/09/2019 |                  |          | Manufacturer           | Manufacturer Service Bulletin<br>Mfr. Recall G5O<br>Warranty Extension: 2016-19 CIVIC A/C<br>CONDENSER WARRANTY EXTENSION<br>LOCATE YOUR NEAREST AUTHORIZED<br><a href="#">HONDA DEALER</a> TO SCHEDULE REPAIR.<br>Status: Remedy Unknown                         |
| 11/11/2019 | TROUTDALE,<br>OR | 54,288   | Service Record         | Cooling System Serviced<br>Battery Serviced or Replaced<br>Multiple Point Vehicle Inspection<br>Engine Serviced<br>Wipers Replaced And/Or Serviced<br>Tires or Wheels Service Performed<br>Lube, Oil And/Or Filter Changed  |
| 11/26/2019 | TROUTDALE,<br>OR | 54,923   | Service Record         | Recommended Maintenance Performed<br>Transmission Serviced<br>Brakes Serviced   |
| 02/11/2020 | CORBETT, OR      |          | Motor Vehicle<br>Dept. | Registration Event/Renewal  |
| 08/20/2020 | TROUTDALE,<br>OR | 64,036   | Service Record         | Multiple Point Vehicle Inspection<br>Engine Serviced<br>Tires or Wheels Service Performed<br>Lube, Oil And/Or Filter Changed  |
| 08/17/2021 | TROUTDALE,<br>OR | 72,287   | Service Record         | Air Filter Changed<br>Multiple Point Vehicle Inspection<br>Engine Serviced<br>Recommended Maintenance Performed<br>Brakes Serviced<br>Tires or Wheels Service Performed<br>Lube, Oil And/Or Filter Changed  |
| 12/27/2021 | TROUTDALE,<br>OR | 77,284   | Service Record         | Battery Serviced or Replaced  |
| 03/23/2022 | CORBETT, OR      |          | Motor Vehicle<br>Dept. | Registration Event/Renewal  |
| 06/06/2022 | TROUTDALE,<br>OR | 83,146   | Service Record         | Heat or Air Conditioning Serviced<br>Multiple Point Vehicle Inspection  |
| 03/09/2023 | TROUTDALE,<br>OR | 89,321   | Service Record         | Cooling System Serviced<br>Multiple Point Vehicle Inspection<br>Engine Serviced   |

| Event Date | Location        | Odometer | Data Source         | Details  |
|------------|-----------------|----------|---------------------|--|
|            |                 |          |                     | Tires or Wheels Service Performed<br>Lube, Oil And/Or Filter Changed |
| 03/28/2024 | OR              | 94,072   | Motor Vehicle Dept. | Passed Emission Inspection   |
| 05/14/2024 | PORTLAND,<br>OR |          | Motor Vehicle Dept. | Registration Event/Renewal   |
| 07/31/2024 | PORTLAND,<br>OR |          | Motor Vehicle Dept. | Registration Event/Renewal   |
| 02/18/2026 | PORTLAND,<br>OR |          | Motor Vehicle Dept. | Registration Event/Renewal   |
| 02/18/2026 | OR              | 102,280  | Motor Vehicle Dept. | Passed Emission Inspection   |
| 2016       |                 |          |                     |  |

[Vehicle Prep and Other Pre-Titling Events](#)

**Location:** OR

**Preparation Date:** 03/2016

Event Date - 03/22/2016

Location - OR

Odometer - 30

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

2016

[Owner 1](#)

**Location:** OR

**Owned From:** 04/2016

**Usage:** Personal

Event Date - 04/27/2016

Location - CORBETT, OR

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Registration Event/Renewal

Event Date - 05/06/2016

Location - CORBETT, OR

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)  
Registration Event/Renewal

Event Date - 04/07/2017

Location -

Odometer - 16,722

Data Source - Service Record

Details - Multiple Point Vehicle Inspection  
Engine Serviced  
Recommended Maintenance Performed  
Wipers Replaced And/Or Serviced  
Brakes Serviced  
Lights or Signals Serviced  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed

Event Date - 11/21/2017

Location -

Odometer - 25,836

Data Source - Service Record

Details - Air Filter Changed  
Multiple Point Vehicle Inspection  
Engine Serviced  
Recommended Maintenance Performed  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed  
Vehicle Fluids Serviced

Event Date - 06/11/2018

Location -

Odometer - 34,968

Data Source - Service Record

Details - Multiple Point Vehicle Inspection  
Engine Serviced  
Recommended Maintenance Performed  
Brakes Serviced  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed  
Vehicle Fluids Serviced

Event Date - 12/11/2018

Location -

Odometer - 41,949

Data Source - Service Record

Details - Tires or Wheels Service Performed

Event Date - 03/20/2019

Location -

Odometer - 45,450

Data Source - Service Record

Details - Heat or Air Conditioning Serviced

Air Filter Changed

Multiple Point Vehicle Inspection

Engine Serviced

Recommended Maintenance Performed

Tires or Wheels Service Performed

Lube, Oil And/Or Filter Changed

Event Date - 08/09/2019

Location -

Data Source - Manufacturer

Details - Manufacturer Service Bulletin

Mfr. Recall G50

Warranty Extension: 2016-19 CIVIC A/C CONDENSER WARRANTY EXTENSION

LOCATE YOUR NEAREST AUTHORIZED

[HONDA DEALER](#) TO SCHEDULE REPAIR.

Status: Remedy Unknown

Event Date - 11/11/2019

Location - TROUTDALE, OR

Odometer - 54,288

Data Source - Service Record

Details - Cooling System Serviced

Battery Serviced or Replaced

Multiple Point Vehicle Inspection

Engine Serviced

Wipers Replaced And/Or Serviced

Tires or Wheels Service Performed

Lube, Oil And/Or Filter Changed

Event Date - 11/26/2019

Location - TROUTDALE, OR

Odometer - 54,923

Data Source - Service Record

Details - Recommended Maintenance Performed  
Transmission Serviced  
Brakes Serviced

Event Date - 02/11/2020

Location - CORBETT, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 08/20/2020

Location - TROUTDALE, OR

Odometer - 64,036

Data Source - Service Record

Details - Multiple Point Vehicle Inspection  
Engine Serviced  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed

Event Date - 08/17/2021

Location - TROUTDALE, OR

Odometer - 72,287

Data Source - Service Record

Details - Air Filter Changed  
Multiple Point Vehicle Inspection  
Engine Serviced  
Recommended Maintenance Performed  
Brakes Serviced  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed

Event Date - 12/27/2021

Location - TROUTDALE, OR

Odometer - 77,284

Data Source - Service Record

Details - Battery Serviced or Replaced

Event Date - 03/23/2022

Location - CORBETT, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 06/06/2022

Location - TROUTDALE, OR

Odometer - 83,146

Data Source - Service Record

Details - Heat or Air Conditioning Serviced  
Multiple Point Vehicle Inspection

Event Date - 03/09/2023

Location - TROUTDALE, OR

Odometer - 89,321

Data Source - Service Record

Details - Cooling System Serviced  
Multiple Point Vehicle Inspection  
Engine Serviced  
Tires or Wheels Service Performed  
Lube, Oil And/Or Filter Changed

Event Date - 03/28/2024

Location - OR

Odometer - 94,072

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 05/14/2024

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 07/31/2024

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 02/18/2026

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 02/18/2026

Location - OR

Odometer - 102,280

Data Source - Motor Vehicle Dept.








Details - Passed Emission Inspection

 Warranty Check [Warranty Check](#) [Back To Top](#)

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Enter Mileage:

 miles

| Coverage Type   | Remaining Miles | Remaining Time | Status  | Coverage Details  |
|---|-----------------|----------------|---|---|
| Basic                 | -               | -              |  Expired  | 36 months / 36000 miles   |
| Battery              | -               | -              | -   | Contact a certified dealer to verify coverage   |
| Corrosion            | -               | -              |  Expired | 60 months / Unlimited miles   |
| Powertrain           | -               | -              |  Expired | 60 months / 60000 miles   |
| Roadside Assistance  | -               | -              |  Expired | 36 months / 36000 miles   |
|   |                 |                |   | 180 months / 150000 miles   |
| Safety Restraint     | 45,120          | 58 months      |  Active  | Honda will repair or replace, at its option, any Honda seat belt component that fails to function properly during normal use. This includes all parts and labor charges. <a href="#">See more</a> |

This Vehicle's Glossary [Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

Term

Section Location

Definition

State Title Brand

Vehicle History at a Glance

A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire,

Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

#### Auction Issue

##### Vehicle History at a Glance

This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

#### Accident/Damage Check

##### Vehicle History at a Glance

This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

#### Insurance Loss/Title Transfer

##### Vehicle History at a Glance

This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

#### Additional History

##### Vehicle History at a Glance

This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

#### Odometer Check

##### Vehicle History at a Glance

This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

#### Loan/Lien

##### Additional History

A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

#### Personal Use

##### Owner Type

This vehicle was driven for personal use.

#### **Term - State Title Brand**

#### **Section Location - Vehicle History at a Glance**

**Definition** - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

#### **Term - Auction Issue**

#### **Section Location - Vehicle History at a Glance**

**Definition** - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

**Term** - Accident/Damage Check

**Section Location** - Vehicle History at a Glance

**Definition** - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

**Term** - Insurance Loss/Title Transfer

**Section Location** - Vehicle History at a Glance

**Definition** - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

**Term** - Additional History

**Section Location** - Vehicle History at a Glance

**Definition** - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

**Term** - Odometer Check

**Section Location** - Vehicle History at a Glance

**Definition** - This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

**Term** - Loan/Lien

**Section Location** - Additional History

**Definition** - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

**Term** - Personal Use

**Section Location** - Owner Type

**Definition** - This vehicle was driven for personal use.