

Print Report



Experian AutoCheck Report

Report run: 07/14/2026 14:41:02 EDT
2014 Audi A4 allroad 2.0T quattro Premium
Wagon 4D (2.0L I4 DI Flex Fuel)
VIN:
WA1TFAFL4EA087352
Class:
Car - Compact Luxury
Country of Assembly:
Germany
Vehicle Age:
12 year(s)
Estimated In Service:
01/18/2014
Last Reported Odometer:
176,714 (06/04/2026)

[View Vehicle Label](#)

Owners - 3

Number of Owners

Vehicle Usage

Lease

x

Window Sticker

Loading window sticker...



[Download PDF](#)

Vehicle History at a Glance

vhg-title-brand-no-issue

State Title Brand

icon-more-information

Clean

auction brand icon

Auction Brand / Issues


icon-success-pass

No Issue


vhg-accident-damage-no-issue

Accident / Damage

No Accidents or Damage Reported




No Issue




Open Recall Check




2 Open Recall(s)



Insurance Loss / Transfer




No Issue




Odometer Check

Last reported odometer:


176,714 (06/04/2026)




No Issue



Certified Pre-Owned




No CPO Info Available




Service / Repair

12 Service Record(s) Reported



No Issue



Additional History

Lien Reported






Events Reported



This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

[Learn More](#)



 accident-overturned-off Overturned

 accident-severe-off No Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.

 Open Safety Recall Open Recall Check [Back To Top](#)

 More Information

Information Reported: AutoCheck found 2 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date

Recall Type

NHTSA / OEM Recall No.

Campaign Description

10/23/2014

Safety

N/A / 69K5

Safety Recall: AIRBAG CONTROL UNIT DEPLOYMENT PARAMETER

Status: Remedy Unknown

10/31/2017

Safety

N/A / 80C5

Safety Recall: AUXILLARY HEATER

Status: Remedy Unknown

Recall Date - 10/23/2014

Recall Type - Safety

NHTSA / OEM Recall No. - N/A / 69K5

Campaign Description - Safety Recall: AIRBAG CONTROL UNIT DEPLOYMENT PARAMETER

Status: Remedy Unknown

Recall Date - 10/31/2017

Recall Type - Safety

NHTSA / OEM Recall No. - N/A / 80C5

Campaign Description - Safety Recall: AUXILLARY HEATER

Status: Remedy Unknown

[More information](#) including remedy or risk factors. Locate your nearest authorized [Audi Dealer](#) to schedule repair.

 Service History Summary Icon [Back To Top](#)

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

 Service History Summary Icon

Regular Oil Changes

- **3** oil services reported
- Last oil service reported **12/30/2025**

 Service History Summary Icon

Fluids Maintained

- **3** coolant flushes
- Last fluid maintained **12/30/2025**

 Service History Summary Icon

Brakes Maintained

- **8** brake pad replacements
- Brake last maintained on **06/04/2026**

 Service History Summary Icon

Tires Maintained

Information not available.

 Service History Summary Icon

A/C & Climate Control

- **3** A/C services reported
- A/C system last serviced **06/04/2026**

 Service History Summary Icon

Other Services

- Battery replaced on **12/30/2025**

OEM Recommended Services

 Service History Summary Icon

175000 Mile Service

- Automatic transmission and final drive - Check for leaks
- Battery - Check for clean terminals (no corrosion), properly mounted housing and no damage; replace if necessary. Also, check the acid level of battery only if the level can be seen through the housing and fill if necessary
- Battery - Small 12 volt side battery located in the trunk compartment on left side. Check for clean terminals (no corrosion), properly mounted housing and no damage; replace if necessary

Service History Summary Icon

185000 Mile Service Not Yet Due

- Brake system - Check for damage and leaks, thickness of pads, and brake fluid level
- #NAME?
- Perform first at 35,000 miles or 6 years, whichever occurs first. Thereafter, every 30,000 miles or 6 years, whichever occurs first

[See more](#)

OEM Recommended Services



Please contact your local dealer or visit the OEM's website for details.

Service History Summary Icon

175000 Mile Service

- Automatic transmission and final drive - Check for leaks
- Battery - Check for clean terminals (no corrosion), properly mounted housing and no damage; replace if necessary. Also, check the acid level of battery only if the level can be seen through the housing and fill if necessary
- Battery - Small 12 volt side battery located in the trunk compartment on left side. Check for clean terminals (no corrosion), properly mounted housing and no damage; replace if necessary
- Cooling system - Check coolant level and add coolant if necessary
- Drive shafts - Check boots
- Engine compartment - Check for leaks
- Exhaust system - Check for damage and leaks
- Front and rear axle - Check for excessive play. Check dust seals on ball joints and tie rod ends
- Horn - Check function
- Lighting, Front - Check function of parking lights, low beams, high beams, fog lights, blinkers and hazard lights
- Lighting, Rear - Check function of brake lights (including third brake light), ail lights, back-up lights, rear fog lights, license plate lights, blinkers and hazard lights
- Manual Transmission and Final Drive - Check for leaks
- Perform first at 15,000 miles and thereafter every 20,000 miles
- Perform first at 55,000 miles and thereafter every 60,000 miles

- Road test - Check engine performance, clutch, manual/auto transmission, braking (including hand and foot brake), steering, wheels, wheel bearings, drive shaft, horn, hybrid vehicles (electric drive for operational readiness)
- Snow screen for air cleaner - Clean
- Sunroof systems - Check function
- Tire repair set - Check for completeness and renewal date (where applicable)
- Underbody - Check for damage and leaks
- Visual check - Check that the wheel house liners, underbody paneling and lines are correctly mounted
- Visual check - Check the chassis for possible paint damage and corrosion, from the inside and outside with the doors as well as hood and trunk lids open
- Windshield washer and headlight washing system - Add fluid if necessary. Check adjustment and function
- Wiper blades - Check condition and replace if necessary

Service History Summary Icon

185000 Mile Service Not Yet Due

- Brake system - Check for damage and leaks, thickness of pads, and brake fluid level
- #NAME?
- Perform first at 35,000 miles or 6 years, whichever occurs first. Thereafter, every 30,000 miles or 6 years, whichever occurs first

Close

 Odometer Dial Odometer Check [Back To Top](#)

 icon-success-pass

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

 icon-success-pass

State Title Odometer Check

No issues reported

 icon-success-pass

Auction Odometer Check

No issues reported

 icon-success-pass

Odometer Calculation Check

No issues reported

 Detailed Vehicle History Icon Detailed Vehicle History [Back To Top](#)

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2014 Audi A4 allroad 2.0T quattro Premium (WA1TFAFL4EA087352) **Report Run Date:** 07/14/2026 14:41:02 EDT

2014

[Vehicle Prep and Other Pre-Titling Events](#)

Preparation Date: 01/2014

Event Date	Location	Odometer	Data Source	Details
01/18/2014			Independent Source	Vehicle Manufactured and Shipped to Dealer
01/27/2014			Independent Source	Vehicle Manufactured and Shipped to Dealer
02/24/2014	CA	10	Motor Vehicle Dept.	Odometer Reading from DMV

2014

[Owner 1](#)

Location: CA

Owned From: 03/2014

Usage: Lease

Event Date	Location	Odometer	Data Source	Details
03/16/2014	LIVERMORE, CA		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
03/17/2014	CA		Motor Vehicle Dept.	Title(Leased Vehicle)(Lien Reported)
03/27/2014	CA		Motor Vehicle Dept.	Title(Leased Vehicle)(Lien Reported)
09/14/2014			Independent Source	Vehicle Manufactured and Shipped to Dealer
09/14/2014	CA	7,244	Motor Vehicle Dept.	Odometer Reading from DMV

2014

[Owner 2](#)

Location: CA

Owned From: 10/2014

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
10/09/2014	LIVERMORE, CA		Motor Vehicle Dept.	Registration Event/Renewal
10/10/2014	LIVERMORE, CA		Motor Vehicle Dept.	Title(Lien Reported)
10/23/2014			Manufacturer	Manufacturer Recall Mfr. Recall 69K5 Safety Recall: AIRBAG CONTROL UNIT DEPLOYMENT PARAMETER

Event Date	Location	Odometer	Data Source	Details
				LOCATE YOUR NEAREST AUTHORIZED AUDI DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
11/18/2014	LIVERMORE, CA		Motor Vehicle Dept.	Registration Event/Renewal
10/31/2017			Manufacturer	Manufacturer Recall Mfr. Recall 80C5 Safety Recall: AUXILLARY HEATER LOCATE YOUR NEAREST AUTHORIZED AUDI DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
07/23/2021	LIVERMORE, CA		Motor Vehicle Dept.	Title(Lien Reported)
07/31/2021	LIVERMORE, CA		Motor Vehicle Dept.	Registration Event/Renewal
02/23/2022	CA	120,448	Motor Vehicle Dept.	Passed Emission Inspection
08/22/2022	SANTA BARBARA, CA	127,381	Service Record	Steering System Serviced Multiple Point Vehicle Inspection Engine Serviced Wipers Replaced And/Or Serviced Brakes Serviced Drive Line Serviced Suspension Serviced Tires or Wheels Service Performed
11/27/2022	CA	130,462	Motor Vehicle Dept.	Odometer Reading from DMV
02/22/2023	SANTA BARBARA, CA	133,563	Service Record	Steering System Serviced Fuel System Serviced Multiple Point Vehicle Inspection Engine Serviced Wipers Replaced And/Or Serviced
02/22/2023	SANTA BARBARA, CA		Service Record	Exhaust System Serviced
02/22/2023	SANTA BARBARA, CA		Service Record	Brakes Serviced Suspension Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced

2023

[Owner 3](#)

Location: CA

Owned From: 05/2023

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
05/09/2023	GOLETA, CA		Motor Vehicle Dept.	Title Registration Event/Renewal Steering System Serviced Multiple Point Vehicle Inspection Engine Serviced
09/07/2023	SANTA BARBARA, CA	144,257	Service Record	Wipers Replaced And/Or Serviced Brakes Serviced Suspension Serviced Tires or Wheels Service Performed
10/17/2023	SANTA BARBARA, CA	145,678	Service Record	Steering System Serviced Fuel System Serviced Emission System Serviced Multiple Point Vehicle Inspection Engine Serviced
10/17/2023	SANTA BARBARA, CA		Service Record	Wipers Replaced And/Or Serviced Brakes Serviced Suspension Serviced Tires or Wheels Service Performed
11/28/2023	GOLETA, CA		Motor Vehicle Dept.	Registration Event/Renewal
03/25/2024	SANTA BARBARA, CA	153,525	Service Record	Steering System Serviced Fuel System Serviced Multiple Point Vehicle Inspection Engine Serviced
03/25/2024	SANTA BARBARA, CA		Service Record	Wipers Replaced And/Or Serviced Brakes Serviced Drive Line Serviced Suspension Serviced Tires or Wheels Service Performed
11/22/2024	CA	161,331	Motor Vehicle Dept.	Failed Emission Inspection Steering System Serviced Cooling System Serviced Fuel System Serviced Multiple Point Vehicle Inspection Engine Serviced
06/25/2025	SANTA BARBARA, CA	166,291	Service Record	Wipers Replaced And/Or Serviced Brakes Serviced Drive Line Serviced Lights or Signals Serviced Suspension Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
07/31/2025	CA	167,440	Motor Vehicle Dept.	Passed Emission Inspection
12/30/2025	SANTA BARBARA, CA	172,126	Service Record	Steering System Serviced Cooling System Serviced Fuel System Serviced Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Wipers Replaced And/Or Serviced Brakes Serviced

Event Date	Location	Odometer	Data Source	Details
				Drive Line Serviced Lights or Signals Serviced Suspension Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced Steering System Serviced Cooling System Serviced Multiple Point Vehicle Inspection Engine Serviced Wipers Replaced And/Or Serviced Brakes Serviced Suspension Serviced Tires or Wheels Service Performed
06/04/2026	SANTA BARBARA, CA	176,714	Service Record	

2014

[Vehicle Prep and Other Pre-Titling Events](#)

Preparation Date: 01/2014

Event Date - 01/18/2014

Location -

Data Source - Independent Source

Details - Vehicle Manufactured and Shipped to Dealer

Event Date - 01/27/2014

Location -

Data Source - Independent Source

Details - Vehicle Manufactured and Shipped to Dealer

Event Date - 02/24/2014

Location - CA

Odometer - 10

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

2014

[Owner 1](#)

Location: CA

Owned From: 03/2014

Usage: Lease

Event Date - 03/16/2014

Location - LIVERMORE, CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal(Leased Vehicle)

Event Date - 03/17/2014

Location - CA

Data Source - Motor Vehicle Dept.

Details - Title(Leased Vehicle)(Lien Reported)

Event Date - 03/27/2014

Location - CA

Data Source - Motor Vehicle Dept.

Details - Title(Leased Vehicle)(Lien Reported)

Event Date - 09/14/2014

Location -

Data Source - Independent Source

Details - Vehicle Manufactured and Shipped to Dealer

Event Date - 09/14/2014

Location - CA

Odometer - 7,244

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

2014

[Owner 2](#)

Location: CA
Owned From: 10/2014
Usage: Personal

Event Date - 10/09/2014

Location - LIVERMORE, CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 10/10/2014

Location - LIVERMORE, CA

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Event Date - 10/23/2014

Location -

Data Source - Manufacturer

Details - Manufacturer Recall

Mfr. Recall 69K5

Safety Recall: AIRBAG CONTROL UNIT DEPLOYMENT PARAMETER
LOCATE YOUR NEAREST AUTHORIZED
[AUDI DEALER](#) TO SCHEDULE REPAIR.

Status: Remedy Unknown

Event Date - 11/18/2014

Location - LIVERMORE, CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 10/31/2017

Location -

Data Source - Manufacturer

Details - Manufacturer Recall

Mfr. Recall 80C5

Safety Recall: AUXILLARY HEATER
LOCATE YOUR NEAREST AUTHORIZED
[AUDI DEALER](#) TO SCHEDULE REPAIR.

Status: Remedy Unknown

Event Date - 07/23/2021

Location - LIVERMORE, CA

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Event Date - 07/31/2021

Location - LIVERMORE, CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 02/23/2022

Location - CA

Odometer - 120,448

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 08/22/2022

Location - SANTA BARBARA, CA

Odometer - 127,381

Data Source - Service Record

Details - Steering System Serviced
Multiple Point Vehicle Inspection
Engine Serviced
Wipers Replaced And/Or Serviced
Brakes Serviced
Drive Line Serviced
Suspension Serviced
Tires or Wheels Service Performed

Event Date - 11/27/2022

Location - CA

Odometer - 130,462

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

Event Date - 02/22/2023

Location - SANTA BARBARA, CA

Odometer - 133,563

Data Source - Service Record

Details - Steering System Serviced
Fuel System Serviced
Multiple Point Vehicle Inspection
Engine Serviced
Wipers Replaced And/Or Serviced

Event Date - 02/22/2023

Location - SANTA BARBARA, CA

Data Source - Service Record

Details - Exhaust System Serviced

Event Date - 02/22/2023

Location - SANTA BARBARA, CA

Data Source - Service Record

Details - Brakes Serviced
Suspension Serviced
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Vehicle Fluids Serviced

2023

[Owner 3](#)

Location: CA
Owned From: 05/2023
Usage: Personal

Event Date - 05/09/2023

Location - GOLETA, CA

Data Source - Motor Vehicle Dept.

Details - Title
Registration Event/Renewal

Event Date - 09/07/2023

Location - SANTA BARBARA, CA

Odometer - 144,257

Data Source - Service Record

Details - Steering System Serviced
Multiple Point Vehicle Inspection
Engine Serviced
Wipers Replaced And/Or Serviced
Brakes Serviced
Suspension Serviced
Tires or Wheels Service Performed

Event Date - 10/17/2023

Location - SANTA BARBARA, CA

Odometer - 145,678

Data Source - Service Record

Details - Steering System Serviced

Event Date - 10/17/2023

Location - SANTA BARBARA, CA

Data Source - Service Record

Details - Fuel System Serviced
Emission System Serviced
Multiple Point Vehicle Inspection
Engine Serviced
Wipers Replaced And/Or Serviced
Brakes Serviced
Suspension Serviced
Tires or Wheels Service Performed

Event Date - 11/28/2023

Location - GOLETA, CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 03/25/2024

Location - SANTA BARBARA, CA

Odometer - 153,525

Data Source - Service Record

Details - Steering System Serviced

Event Date - 03/25/2024

Location - SANTA BARBARA, CA

Data Source - Service Record

Details - Fuel System Serviced
Multiple Point Vehicle Inspection
Engine Serviced
Wipers Replaced And/Or Serviced
Brakes Serviced
Drive Line Serviced
Suspension Serviced
Tires or Wheels Service Performed

Event Date - 11/22/2024

Location - CA

Odometer - 161,331

Data Source - Motor Vehicle Dept.

Details - Failed Emission Inspection

Event Date - 06/25/2025

Location - SANTA BARBARA, CA

Odometer - 166,291

Data Source - Service Record

Details - Steering System Serviced
Cooling System Serviced
Fuel System Serviced
Multiple Point Vehicle Inspection
Engine Serviced
Wipers Replaced And/Or Serviced
Brakes Serviced
Drive Line Serviced
Lights or Signals Serviced
Suspension Serviced
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed
Vehicle Fluids Serviced

Event Date - 07/31/2025

Location - CA

Odometer - 167,440

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 12/30/2025

Location - SANTA BARBARA, CA

Odometer - 172,126

Data Source - Service Record

- Details - Steering System Serviced
- Cooling System Serviced
- Fuel System Serviced
- Battery Serviced or Replaced
- Multiple Point Vehicle Inspection
- Engine Serviced
- Wipers Replaced And/Or Serviced
- Brakes Serviced
- Drive Line Serviced
- Lights or Signals Serviced
- Suspension Serviced
- Tires or Wheels Service Performed
- Lube, Oil And/Or Filter Changed
- Vehicle Fluids Serviced

Event Date - 06/04/2026

Location - SANTA BARBARA, CA

Odometer - 176,714

Data Source - Service Record

- Details - Steering System Serviced
- Cooling System Serviced
- Multiple Point Vehicle Inspection
- Engine Serviced
- Wipers Replaced And/Or Serviced
- Brakes Serviced
- Suspension Serviced
- Tires or Wheels Service Performed

Warranty Check [Back To Top](#)

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Enter Mileage:

 miles

Show My Coverage

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-	 Expired	48 months / 50000 miles
Battery 	-	-	-	Contact a certified dealer to verify coverage
Corrosion 	-	-	 Expired	144 months / Unlimited miles
Powertrain 	-	-	 Expired	48 months / 50000 miles
Roadside Assistance 	-	-	 Expired	48 months / Unlimited miles

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Safety Restraint 	-	-	-	Contact a certified dealer to verify coverage
This Vehicle's GlossaryBack To Top More information is available in the full AutoCheck glossary.				
Term Section Location Definition State Title Brand Vehicle History at a Glance A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.				
Auction Issue Vehicle History at a Glance This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the National Auction Automotive Association Arbitration Policy 2025.				
Accident/Damage Check Vehicle History at a Glance This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.				
Insurance Loss/Title Transfer Vehicle History at a Glance This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.				
Additional History Vehicle History at a Glance This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.				
Odometer Check Vehicle History at a Glance This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.				
Open Recall Check Vehicle History at a Glance This section lists any open safety or emission recalls on the vehicle that may need to be fulfilled.				
Loan/Lien Additional History				

A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Lease Use

Owner Type

Vehicle was registered as lease vehicle.

Open Recall

Open Recall Check

A recall is considered 'open' for a vehicle when it has not received the required service to correct the identified recall. The vehicle will need to be taken to a repair center that has been authorized by the manufacturer to correct any open recall conditions.

Term - State Title Brand

Section Location - Vehicle History at a Glance

Definition - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Term - Auction Issue

Section Location - Vehicle History at a Glance

Definition - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Accident/Damage Check

Section Location - Vehicle History at a Glance

Definition - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Term - Insurance Loss/Title Transfer

Section Location - Vehicle History at a Glance

Definition - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Term - Additional History

Section Location - Vehicle History at a Glance

Definition - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Term - Odometer Check

Section Location - Vehicle History at a Glance

Definition - This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Term - Open Recall Check

Section Location - Vehicle History at a Glance

Definition - This section lists any open safety or emission recalls on the vehicle that may need to be fulfilled.

Term - Loan/Lien

Section Location - Additional History

Definition - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Term - Lease Use

Section Location - Owner Type

Definition - Vehicle was registered as lease vehicle.

Term - Open Recall

Section Location - Open Recall Check

Definition - A recall is considered 'open' for a vehicle when it has not received the required service to correct the identified recall. The vehicle will need to be taken to a repair center that has been authorized by the manufacturer to correct any open recall conditions.