

Print Report



Experian AutoCheck Report

Report run: 07/13/2026 14:57:49 EDT

2013 Hyundai Elantra Coupe GS / SE

Coupe 2D (1.8L I4 SEFI Gasoline)

VIN:

KMMDH6AE7DU006833

Class:

Car - Compact

Country of Assembly:

South Korea

Vehicle Age:

13 year(s)

Estimated In Service:

08/21/2012

Last Reported Odometer:

113,341 (01/21/2021)

[View Vehicle Label](#)

Number of Owners

Vehicle Usage

Personal

x

Window Sticker

Loading window sticker...



[Download PDF](#)

Vehicle History at a Glance

vhg-title-brand-no-issue

State Title Brand

icon-more-information

Clean

auction brand icon

Auction Brand / Issues

icon-success-pass

No Issue

vhg-accident-damage-no-issue

Accident / Damage

No Accidents or Damage Reported

icon-success-pass

No Issue

 recall check icon

Open Recall Check

 icon-more-information

1 Open Recall(s)

 vhg-insurance-loss-title-no-issue

Insurance Loss / Transfer

 icon-success-pass

No Issue

 vhg-odometer-check-no-issue

Odometer Check

Last reported odometer:

113,341 (01/21/2021)

 icon-success-pass

No Issue

 cpo icon

Certified Pre-Owned

 icon-success-pass

No CPO Info Available

 service repair icon

Service / Repair

4 Service Record(s) Reported

 icon-success-pass

No Issue

 vhg-additional-history-issue-found

Additional History

Lien Reported, Duplicate Title

 icon-more-information

Events Reported

 vhg-title-brand-no-issue

This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

[Learn More](#)

 damage icon Accident & Damage [Back To Top](#)

 accident-car-outline-no-impact

 accident-airbag-deployed-off Airbag Deployed

 accident-structural-damage-off Structural Damage

 accident-overturned-off Overturned

 accident-severe-off No Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.

 Inspection Check Inspection History Check [Back To Top](#)

 icon-more-information

Information Reported

Below are inspection(s) that were reported for this vehicle. Please note that not all inspections are reported to Experian AutoCheck.

Inspection Date

Location

Odometer Reading

Data Source

Details

01/10/2013

CORNING, NY

3,024

Independent Source

Independent Inspection/Theft Deterrent Equipped

Inspection Date - 01/10/2013

Location - CORNING, NY

Odometer Reading - 3,024

Data Source - Independent Source

Details - Independent Inspection/Theft Deterrent Equipped

 Open Safety Recall Open Recall Check [Back To Top](#)

 More Information

Information Reported: AutoCheck found 1 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date

Recall Type

NHTSA / OEM Recall No.

Campaign Description

04/03/2024

Unspecified

23V651000 / 251

ABS FUSE REPLACEMENT (VARIOUS MODELS)

Status: Remedy Unknown

Recall Date - 04/03/2024

Recall Type - Unspecified

NHTSA / OEM Recall No. - 23V651000 / 251

Campaign Description - ABS FUSE REPLACEMENT (VARIOUS MODELS)

Status: Remedy Unknown

[More information](#) including remedy or risk factors. Locate your nearest authorized [Hyundai Dealer](#) to schedule repair.

 Service History Summary Icon Service History [Back To Top](#)

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

 Service History Summary Icon

Regular Oil Changes

- **3** oil services reported
- Last oil service reported **12/18/2019**

 Service History Summary Icon

Fluids Maintained

- **1** coolant flushes
- Last fluid maintained **12/18/2019**

 Service History Summary Icon

Brakes Maintained

- **1** brake pad replacements
- Brake last maintained on **04/23/2013**

 Service History Summary Icon

Tires Maintained

Information not available.

 Service History Summary Icon

A/C & Climate Control

Information not available.

 Service History Summary Icon

Other Services

Information not available.

OEM Recommended Services

 Service History Summary Icon

112500 Mile Service

- Add Fuel Additive (recommended only if TOP TIER Detergent Gasoline is not available. See owner's manual for details.)
- Inspect Air Cleaner Filter
- Inspect Battery Condition

 Service History Summary Icon

120000 Mile Service Not Yet Due

- Add Fuel Additive (recommended only if TOP TIER Detergent Gasoline is not available. See owner's manual for details.)
- Inspect Air Conditioning Refrigerant
- Inspect Battery Condition

[See more](#)

OEM Recommended Services



Please contact your local dealer or visit the OEM's website for details.

 Service History Summary Icon

112500 Mile Service

- Add Fuel Additive (recommended only if TOP TIER Detergent Gasoline is not available. See owner's manual for details.)
- Inspect Air Cleaner Filter
- Inspect Battery Condition
- Inspect Vacuum Hose
- Replace Engine Oil and Filter
- Tire Rotation

 Service History Summary Icon

120000 Mile Service Not Yet Due

- Add Fuel Additive (recommended only if TOP TIER Detergent Gasoline is not available. See owner's manual for details.)
- Inspect Air Conditioning Refrigerant
- Inspect Battery Condition
- Inspect Brake Fluid

- Inspect Brake Hoses and Lines
- Inspect Drive Belt(s)
- Inspect Driveshafts and Boots
- Inspect Exhaust Pipe and Muffler
- Inspect Front Brake Disc/Pads, Calipers
- Inspect Fuel Filter
- Inspect Fuel Lines, Fuel Hoses, and Connections
- Inspect Fuel Tank Air Filter
- Inspect Parking Brake
- Inspect Rear Brake Disc/Pads
- Inspect Steering Gear Box, Linkage & Boots/Lower Arm Ball Joint, Upper Arm Ball Joint
- Inspect Suspension Mounting Bolts
- Inspect Vacuum Hose
- Inspect Vapor Hose and Fuel Filler Cap
- Replace Air Cleaner Filter
- Replace Climate Control Air Filter (for evaporator and blower unit)
- Replace Coolant
- Replace Engine Oil and Filter
- Tire Rotation

Close

 Odometer Dial Odometer Check [Back To Top](#)

 icon-success-pass

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

 icon-success-pass

State Title Odometer Check

No issues reported

 icon-success-pass

Auction Odometer Check

No issues reported

 icon-success-pass

Odometer Calculation Check

No issues reported

 Detailed Vehicle History Icon Detailed Vehicle History [Back To Top](#)

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2013 Hyundai Elantra Coupe GS / SE (KMHDH6AE7DU006833) **Report Run Date:** 07/13/2026 14:57:49 EDT

2012

[Vehicle Prep and Other Pre-Titling Events](#)

Location: NY

Preparation Date: 08/2012

Event Date	Location	Odometer	Data Source	Details
08/21/2012	NY		Independent Source	Vehicle Manufactured and Shipped to Dealer

2012

[Owner 1](#)

Location: WA

Owned From: 12/2012

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
12/10/2012	ADDISON, NY		Motor Vehicle Dept.	Registration Event/Renewal
01/09/2013	ADDISON, NY	13	Motor Vehicle Dept.	Title(Lien Reported)
01/10/2013	CORNING, NY	3,024	Independent Source	Independent Inspection/Theft Deterrent Equipped
04/23/2013	MA	7,532	Independent Repair Center	Multiple Point Vehicle Inspection Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
12/06/2013	MA	18,822	Independent Repair Center	Multiple Point Vehicle Inspection Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
06/24/2014	FORT COLLINS, CO		Dealer Service	Multiple Point Vehicle Inspection Recommended Maintenance Performed Tires or Wheels Service Performed
11/14/2014	ADDISON, NY		Motor Vehicle Dept.	Registration Event/Renewal
09/15/2016	CA	45,751	Motor Vehicle Dept.	Odometer Reading from DMV
10/04/2016	CA		Motor Vehicle Dept.	Passed Emission Inspection
10/05/2016	CA		Motor Vehicle Dept.	Registration Event/Renewal
08/28/2017	CA	58,318	Motor Vehicle Dept.	Title(Lien Reported) Registration Event/Renewal
06/26/2018	CA		Motor Vehicle Dept.	Registration Event/Renewal
12/18/2019	CHRISTIANSBURG, VA	94,186	Service Record	Multiple Point Vehicle Inspection Engine Serviced Wipers Replaced And/Or Serviced

Event Date	Location	Odometer	Data Source	Details
				Lights or Signals Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
10/27/2020	CA		Motor Vehicle Dept.	Registration Event/Renewal
12/15/2020	CA		Motor Vehicle Dept.	Registration Event/Renewal
12/29/2020	CA		Motor Vehicle Dept.	Title(Lien Reported) Duplicate Title(Lien Reported)
01/09/2021	CA		Motor Vehicle Dept.	Registration Event/Renewal
01/21/2021	VANCOUVER, WA	113,341	Motor Vehicle Dept.	Title(Lien Reported) Registration Event/Renewal
12/22/2021	VANCOUVER, WA		Motor Vehicle Dept.	Registration Event/Renewal
12/23/2022	VANCOUVER, WA		Motor Vehicle Dept.	Registration Event/Renewal
12/14/2023	VANCOUVER, WA		Motor Vehicle Dept.	Registration Event/Renewal
				Manufacturer Recall NHTSA Recall 23V651000 / Mfr. Recall 251 ABS FUSE REPLACEMENT (VARIOUS MODELS) LOCATE YOUR NEAREST AUTHORIZED HYUNDAI DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
04/03/2024			Manufacturer	
12/24/2024	BATTLE GROUND, WA		Motor Vehicle Dept.	Registration Event/Renewal
11/23/2025	BATTLE GROUND, WA		Motor Vehicle Dept.	Registration Event/Renewal
2012				

[Vehicle Prep and Other Pre-Titling Events](#)

Location: NY

Preparation Date: 08/2012

Event Date - 08/21/2012

Location - NY

Data Source - Independent Source

Details - Vehicle Manufactured and Shipped to Dealer

2012

[Owner 1](#)

Location: WA

Owned From: 12/2012

Usage: Personal

Event Date - 12/10/2012

Location - ADDISON, NY

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 01/09/2013

Location - ADDISON, NY

Odometer - 13

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Event Date - 01/10/2013

Location - CORNING, NY

Odometer - 3,024

Data Source - Independent Source

Details - Independent Inspection/Theft Deterrent Equipped

Event Date - 04/23/2013

Location - MA

Odometer - 7,532

Data Source - Independent Repair Center

Details - Multiple Point Vehicle Inspection

Brakes Serviced

Tires or Wheels Service Performed

Lube, Oil And/Or Filter Changed

Event Date - 12/06/2013

Location - MA

Odometer - 18,822

Data Source - Independent Repair Center

Details - Multiple Point Vehicle Inspection
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed

Event Date - 06/24/2014

Location - FORT COLLINS, CO

Data Source - Dealer Service

Details - Multiple Point Vehicle Inspection
Recommended Maintenance Performed
Tires or Wheels Service Performed

Event Date - 11/14/2014

Location - ADDISON, NY

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 09/15/2016

Location - CA

Odometer - 45,751

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

Event Date - 10/04/2016

Location - CA

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 10/05/2016

Location - CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 08/28/2017

Location - CA

Odometer - 58,318

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)
Registration Event/Renewal

Event Date - 06/26/2018

Location - CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/18/2019

Location - CHRISTIANSBURG, VA

Odometer - 94,186

Data Source - Service Record

Details - Multiple Point Vehicle Inspection

Engine Serviced

Wipers Replaced And/Or Serviced

Lights or Signals Serviced

Tires or Wheels Service Performed

Lube, Oil And/Or Filter Changed

Vehicle Fluids Serviced

Event Date - 10/27/2020

Location - CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/15/2020

Location - CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/29/2020

Location - CA

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Duplicate Title(Lien Reported)

Event Date - 01/09/2021

Location - CA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 01/21/2021

Location - VANCOUVER, WA

Odometer - 113,341

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)
Registration Event/Renewal

Event Date - 12/22/2021

Location - VANCOUVER, WA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/23/2022

Location - VANCOUVER, WA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/14/2023

Location - VANCOUVER, WA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/03/2024

Location -

Data Source - Manufacturer

Details - Manufacturer Recall
NHTSA Recall 23V651000 / Mfr. Recall 251
ABS FUSE REPLACEMENT (VARIOUS MODELS)
LOCATE YOUR NEAREST AUTHORIZED
[HYUNDAI DEALER](#) TO SCHEDULE REPAIR.
Status: Remedy Unknown

Event Date - 12/24/2024

Location - BATTLE GROUND, WA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 11/23/2025

Location - BATTLE GROUND, WA

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Warranty Check [Back To Top](#)

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Enter Mileage:

 miles

Show My Coverage

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-	 Expired	60 months / 60000 miles
Battery 	-	-	-	Contact a certified dealer to verify coverage
Corrosion 	-	-	 Expired	84 months / Unlimited miles
Powertrain 	-	-	 Expired	120 months / 100000 miles
Roadside Assistance 	-	-	 Expired	60 months / Unlimited miles
Safety Restraint 	-	-	-	Contact a certified dealer to verify coverage

This Vehicle's Glossary [Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

- Term
- Section Location
- Definition
- State Title Brand
- Vehicle History at a Glance

A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

- Auction Issue
- Vehicle History at a Glance

This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

- Accident/Damage Check
- Vehicle History at a Glance

This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test

vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Insurance Loss/Title Transfer

Vehicle History at a Glance

This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Additional History

Vehicle History at a Glance

This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Odometer Check

Vehicle History at a Glance

This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Open Recall Check

Vehicle History at a Glance

This section lists any open safety or emission recalls on the vehicle that may need to be fulfilled.

Loan/Lien

Additional History

A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Duplicate Title

Additional History

The vehicle had a duplicate title issued by the DMV.

Personal Use

Owner Type

This vehicle was driven for personal use.

Open Recall

Open Recall Check

A recall is considered 'open' for a vehicle when it has not received the required service to correct the identified recall. The vehicle will need to be taken to a repair center that has been authorized by the manufacturer to correct any open recall conditions.

Term - State Title Brand

Section Location - Vehicle History at a Glance

Definition - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Term - Auction Issue

Section Location - Vehicle History at a Glance

Definition - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands,

odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Accident/Damage Check

Section Location - Vehicle History at a Glance

Definition - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Term - Insurance Loss/Title Transfer

Section Location - Vehicle History at a Glance

Definition - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Term - Additional History

Section Location - Vehicle History at a Glance

Definition - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Term - Odometer Check

Section Location - Vehicle History at a Glance

Definition - This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Term - Open Recall Check

Section Location - Vehicle History at a Glance

Definition - This section lists any open safety or emission recalls on the vehicle that may need to be fulfilled.

Term - Loan/Lien

Section Location - Additional History

Definition - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Term - Duplicate Title

Section Location - Additional History

Definition - The vehicle had a duplicate title issued by the DMV.

Term - Personal Use

Section Location - Owner Type

Definition - This vehicle was driven for personal use.

Term - Open Recall

Section Location - Open Recall Check

Definition - A recall is considered 'open' for a vehicle when it has not received the required service to correct the identified recall. The vehicle will need to be taken to a repair center that has been authorized by the manufacturer to correct any open recall conditions.