

Print Report



Experian AutoCheck Report

Report run: 07/13/2026 14:58:38 EDT

2012 Chevrolet Cruze ECO

Sedan 4D (1.4L I4 SMPI Gasoline)

VIN:

1G1PJ5SC1C7226455

Class:

Car - Midsize

Country of Assembly:

United States

Vehicle Age:

14 year(s)

Estimated In Service:

12/22/2011

Last Reported Odometer:

212,330 (02/02/2026)

[View Vehicle Label](#)

Owners - 3

Number of Owners

Vehicle Usage

Personal

x

Window Sticker

Loading window sticker...



[Download PDF](#)

Vehicle History at a Glance

vhg-title-brand-no-issue

State Title Brand

icon-success-pass

Clean

auction brand icon

Auction Brand / Issues


icon-success-pass

No Issue


vhg-accident-damage-no-issue

Accident / Damage


No Accidents or Damage Reported




No Issue




Open Recall Check




No Open Recalls



Insurance Loss / Transfer




No Issue




Odometer Check


Last reported odometer:
212,330 (02/02/2026)




No Issue



Certified Pre-Owned




No CPO Info Available




Service / Repair

12 Service Record(s) Reported



No Issue



Additional History

Lien Reported






Events Reported



This vehicle is AutoCheck Assured™

This vehicle does not have any state title brands or other major problems reported.

[Learn More](#)



 accident-overturned-off Overturned

 accident-severe-off No Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.

 Service History Summary Icon [Back To Top](#)

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

 Service History Summary Icon

Regular Oil Changes

- **1** oil services reported
- Last oil service reported **10/26/2021**

 Service History Summary Icon

Fluids Maintained

Information not available.

 Service History Summary Icon

Brakes Maintained

- **2** brake pad replacements
- Brake last maintained on **10/26/2021**

 Service History Summary Icon

Tires Maintained

Information not available.

 Service History Summary Icon

A/C & Climate Control

- **3** A/C services reported
- A/C system last serviced **07/08/2023**

 Service History Summary Icon

Other Services

- Cabin air filter replaced on **04/16/2020**

OEM Recommended Services

 Service History Summary Icon

150000 Mile Service

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function

[See more](#)

OEM Recommended Services



Please contact your local dealer or visit the OEM's website for details.



Service History Summary Icon

150000 Mile Service

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function
- Check engine coolant and washer fluid
- Check engine oil level and oil life percentage
- Check ignition transmission lock
- Check parking brake (and automatic transmission park mechanism, if applicable)
- Check starter switch
- Check tire inflation
- Check tire sealant expiration date
- Check tires for wear
- Drain, flush, and fill cooling system
- Inspect brake system
- Inspect engine air cleaner filter
- Inspect exhaust system for loose or damaged components
- Inspect fuel system for damage or leaks
- Inspect restraint system components
- Inspect sunroof track and seal (if equipped)
- Inspect wiper blades

- Lubricate body components
- Reset oil life system
- Rotate tires
- Visually check for any leaks or damage
- Visually inspect accessory drive belts
- Visually inspect gas strut for signs of wear, cracks, or other damage
- Visually inspect steering, suspension and chassis components

Close

 Odometer Dial Odometer Check [Back To Top](#)

 icon-success-pass

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

 icon-success-pass

State Title Odometer Check

No issues reported

 icon-success-pass

Auction Odometer Check

No issues reported

 icon-success-pass

Odometer Calculation Check

No issues reported

 Detailed Vehicle History Icon Detailed Vehicle History [Back To Top](#)

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2012 Chevrolet Cruze ECO (1G1PJ5SC1C7226455) **Report Run Date:** 07/13/2026 14:58:38 EDT

2011

[Vehicle Prep and Other Pre-Titling Events](#)

Location: OR

Preparation Date: 12/2011

Event Date	Location	Odometer	Data Source	Details
12/22/2011	OR	10	Motor Vehicle Dept.	Odometer Reading from DMV

2012

[Owner 1](#)

Location: OR
Owned From: 01/2012
Usage: Personal

Event Date	Location	Odometer	Data Source	Details
01/13/2012	SAINT HELENS, OR		Motor Vehicle Dept.	Title(Lien Reported) Registration Event/Renewal
12/23/2015	SAINT HELENS, OR		Motor Vehicle Dept.	Registration Event/Renewal
01/05/2018	SAINT HELENS, OR		Motor Vehicle Dept.	Registration Event/Renewal
10/28/2018	OR	107,008	Motor Vehicle Dept.	Odometer Reading from DMV
11/14/2018	SAINT HELENS, OR		Motor Vehicle Dept.	Title Registration Event/Renewal
12/02/2019	SAINT HELENS, OR		Motor Vehicle Dept.	Registration Event/Renewal
04/15/2020	BEAVERTON, OR	123,814	Dealer Service	Air Filter Changed Multiple Point Vehicle Inspection Lights or Signals Serviced Promotional Service Performed
04/16/2020	SAINT HELENS, OR		Motor Vehicle Dept.	Registration Event/Renewal Air Filter Changed Multiple Point Vehicle Inspection Exhaust System Serviced
04/16/2020	BEAVERTON, OR	123,814	Service Record	Brakes Serviced Electrical System Serviced Lights or Signals Serviced Tires or Wheels Service Performed
04/20/2020	BEAVERTON, OR		Service Record	Vehicle Interior Serviced Engine Serviced
04/20/2020	BEAVERTON, OR		Dealer Service	Vehicle Detailed
05/05/2020	BEAVERTON, OR	123,816	Dealer Record	Vehicle in Dealer Inventory

2020

Owner 2

Location: OR
Owned From: 12/2020
Usage: Personal

Event Date	Location	Odometer	Data Source	Details
12/10/2020	HILLSBORO, OR		Motor Vehicle Dept.	Registration Event/Renewal
12/29/2020	OR	131,455	Service Record	Vehicle Serviced or Inspected
03/01/2021	HILLSBORO, OR	123,827 †	Motor Vehicle Dept.	Title(Lien Reported)
08/07/2021	HILLSBORO, OR		Motor Vehicle Dept.	Title(Lien Reported)
08/11/2021	OR	139,865	Service Record	Cooling System Serviced Multiple Point Vehicle Inspection Engine Serviced

Event Date	Location	Odometer	Data Source	Details
08/17/2021	BEAVERTON, OR	139,950	Service Record	Safety Inspection Performed Multiple Point Vehicle Inspection Exhaust System Serviced Tires or Wheels Service Performed
10/05/2021	HILLSBORO, OR		Motor Vehicle Dept.	Title(Lien Reported)
10/26/2021	OR	143,183	Service Record	Cooling System Serviced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Starting or Charging System Service Performed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
05/27/2022	OR	153,782	Motor Vehicle Dept.	Emission Inspection
06/02/2022	OR	154,192	Service Record	Vehicle Inspected Lights or Signals Serviced
06/03/2022	OR	154,286	Motor Vehicle Dept.	Emission Inspection
06/13/2022	HILLSBORO, OR		Motor Vehicle Dept.	Registration Event/Renewal
06/22/2023	HILLSBORO, OR		Motor Vehicle Dept.	Registration Event/Renewal
06/22/2023	OR	178,767	Motor Vehicle Dept.	Passed Emission Inspection
07/06/2023	HILLSBORO, OR	179,076	Service Record	Cooling System Serviced Heat or Air Conditioning Serviced Multiple Point Vehicle Inspection
07/06/2023	HILLSBORO, OR		Service Record	Engine Serviced Transmission Serviced Electrical System Serviced
07/08/2023	OR		Service Record	Cooling System Serviced Vehicle Inspected Promotional Service Performed
06/24/2025	HILLSBORO, OR		Motor Vehicle Dept.	Registration Event/Renewal
01/07/2026	OR	212,965 †	Motor Vehicle Dept.	Emission Inspection

2026

[Owner 3](#)

Location: OR

Owned From: 01/2026

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
01/30/2026	PORTLAND, OR		Motor Vehicle Dept.	Registration Event/Renewal
02/02/2026	PORTLAND, OR	212,330	Motor Vehicle Dept.	Title

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

2011

[Vehicle Prep and Other Pre-Titling Events](#)

Location: OR

Preparation Date: 12/2011

Event Date - 12/22/2011

Location - OR

Odometer - 10

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

2012

[Owner 1](#)

Location: OR

Owned From: 01/2012

Usage: Personal

Event Date - 01/13/2012

Location - SAINT HELENS, OR

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)
Registration Event/Renewal

Event Date - 12/23/2015

Location - SAINT HELENS, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 01/05/2018

Location - SAINT HELENS, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 10/28/2018

Location - OR

Odometer - 107,008

Data Source - Motor Vehicle Dept.

Details - Odometer Reading from DMV

Event Date - 11/14/2018

Location - SAINT HELENS, OR

Data Source - Motor Vehicle Dept.

Details - Title
Registration Event/Renewal

Event Date - 12/02/2019

Location - SAINT HELENS, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/15/2020

Location - BEAVERTON, OR

Odometer - 123,814

Data Source - Dealer Service

Details - Air Filter Changed
Multiple Point Vehicle Inspection
Lights or Signals Serviced
Promotional Service Performed

Event Date - 04/16/2020

Location - SAINT HELENS, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 04/16/2020

Location - BEAVERTON, OR

Odometer - 123,814

Data Source - Service Record

Details - Air Filter Changed
Multiple Point Vehicle Inspection
Exhaust System Serviced
Brakes Serviced
Electrical System Serviced
Lights or Signals Serviced
Tires or Wheels Service Performed

Event Date - 04/20/2020

Location - BEAVERTON, OR

Data Source - Service Record

Details - Vehicle Interior Serviced
Engine Serviced

Event Date - 04/20/2020

Location - BEAVERTON, OR

Data Source - Dealer Service

Details - Vehicle Detailed

Event Date - 05/05/2020

Location - BEAVERTON, OR

Odometer - 123,816

Data Source - Dealer Record

Details - Vehicle in Dealer Inventory

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

[Owner 2](#)

Location: OR

Owned From: 12/2020

Usage: Personal

Event Date - 12/10/2020

Location - HILLSBORO, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 12/29/2020

Location - OR

Odometer - 131,455

Data Source - Service Record

Details - Vehicle Serviced or Inspected

Event Date - 03/01/2021

Location - HILLSBORO, OR

Odometer - 123,827 †

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Event Date - 08/07/2021

Location - HILLSBORO, OR

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Event Date - 08/11/2021

Location - OR

Odometer - 139,865

Data Source - Service Record

Details - Cooling System Serviced
Multiple Point Vehicle Inspection
Engine Serviced

Event Date - 08/17/2021

Location - BEAVERTON, OR

Odometer - 139,950

Data Source - Service Record

Details - Safety Inspection Performed
Multiple Point Vehicle Inspection
Exhaust System Serviced
Tires or Wheels Service Performed

Event Date - 10/05/2021

Location - HILLSBORO, OR

Data Source - Motor Vehicle Dept.

Details - Title(Lien Reported)

Event Date - 10/26/2021

Location - OR

Odometer - 143,183

Data Source - Service Record

Details - Cooling System Serviced
Multiple Point Vehicle Inspection
Engine Serviced
Brakes Serviced
Starting or Charging System Service Performed
Tires or Wheels Service Performed
Lube, Oil And/Or Filter Changed

Event Date - 05/27/2022

Location - OR

Odometer - 153,782

Data Source - Motor Vehicle Dept.

Details - Emission Inspection

Event Date - 06/02/2022

Location - OR

Odometer - 154,192

Data Source - Service Record

Details - Vehicle Inspected
Lights or Signals Serviced

Event Date - 06/03/2022

Location - OR

Odometer - 154,286

Data Source - Motor Vehicle Dept.

Details - Emission Inspection

Event Date - 06/13/2022

Location - HILLSBORO, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 06/22/2023

Location - HILLSBORO, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 06/22/2023

Location - OR

Odometer - 178,767

Data Source - Motor Vehicle Dept.

Details - Passed Emission Inspection

Event Date - 07/06/2023

Location - HILLSBORO, OR

Odometer - 179,076

Data Source - Service Record

Details - Cooling System Serviced

Event Date - 07/06/2023

Location - HILLSBORO, OR

Data Source - Service Record

Details - Heat or Air Conditioning Serviced

Multiple Point Vehicle Inspection

Engine Serviced

Transmission Serviced

Electrical System Serviced

Event Date - 07/08/2023

Location - OR

Data Source - Service Record

Details - Cooling System Serviced
Vehicle Inspected
Promotional Service Performed

Event Date - 06/24/2025

Location - HILLSBORO, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 01/07/2026

Location - OR

Odometer - 212,965 †

Data Source - Motor Vehicle Dept.

Details - Emission Inspection

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

2026

[Owner 3](#)

Location: OR

Owned From: 01/2026

Usage: Personal

Event Date - 01/30/2026

Location - PORTLAND, OR

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Event Date - 02/02/2026

Location - PORTLAND, OR

Odometer - 212,330

Details - Title

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

Warranty Check Icon Warranty Check[Back To Top](#)

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Enter Mileage:

miles

Show My Coverage

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-	 Expired	36 months / 36000 miles
Battery 	-	-	-	Contact a certified dealer to verify coverage
				72 months / 100000 miles
Corrosion 	-	-	 Expired	Rust-through coverage only, Corrosion coverage is for the first 3 years or 36,000 miles
Powertrain 	-	-	 Expired	60 months / 100000 miles
Roadside Assistance 	-	-	 Expired	60 months / 100000 miles
Safety Restraint 	-	-	-	Contact a certified dealer to verify coverage

This Vehicle's Glossary[Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

- Term
- Section Location
- Definition
- State Title Brand
- Vehicle History at a Glance

A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

- Auction Issue
- Vehicle History at a Glance

This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc.

as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Accident/Damage Check

Vehicle History at a Glance

This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Insurance Loss/Title Transfer

Vehicle History at a Glance

This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Additional History

Vehicle History at a Glance

This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Odometer Check

Vehicle History at a Glance

This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Loan/Lien

Additional History

A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Personal Use

Owner Type

This vehicle was driven for personal use.

Term - State Title Brand

Section Location - Vehicle History at a Glance

Definition - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Term - Auction Issue

Section Location - Vehicle History at a Glance

Definition - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Accident/Damage Check

Section Location - Vehicle History at a Glance

Definition - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Term - Insurance Loss/Title Transfer

Section Location - Vehicle History at a Glance

Definition - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Term - Additional History

Section Location - Vehicle History at a Glance

Definition - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Term - Odometer Check

Section Location - Vehicle History at a Glance

Definition - This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Term - Loan/Lien

Section Location - Additional History

Definition - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Term - Personal Use

Section Location - Owner Type

Definition - This vehicle was driven for personal use.